



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

15 W Yakima Ave, Ste 200 • Yakima, WA 98902-3452 • (509) 575-2490

April 26, 2010

Ms. Jody Cada
United Parcel Service
13035 Gateway Drive Suite #149
Seattle, WA 98168

Daniel E. Agramonte, P.E.
Sierra Piedmont, Inc
12045 Highway 92
Woodstock, GA 30188

Dear Ms. Cada and Mr. Agramonte:

The State of Washington Department of Ecology (Ecology) received a work plan for limited subsurface investigation at UPS Union Gap (FSID # 14724678, UST # 3704) on April 20, 2010. After review of the work plan Ecology recommends:

1. Extending the top of the screen interval to within 5 feet below ground surface (bgs). This area of the Yakima Valley experiences dramatic groundwater fluctuations ($\Delta 15$ feet) due to irrigation. Groundwater level data collected by Black & Veatch, for UPS, found the water table at 7.08 feet and 6.84 feet bgs.
2. After the well is developed, wait 48 hours to allow an opportunity for groundwater geochemistry to stabilize.

In accordance with WAC 173-340-840(5) and Ecology Toxics Cleanup Program Policy 840 (Data Submittal Requirements), data generated for Independent Remedial Actions shall be submitted simultaneously in both a written and electronic format. For additional information regarding electronic format requirements, see the website <http://www.ecy.wa.gov/eim>.

Please contact me at (509) 454-7834 if you have any questions regarding this letter.

Sincerely,

A handwritten signature in black ink, appearing to read "Jason Shira".

Jason Shira
Site Manager
Toxics Cleanup Program

