

Department of Ecology - Environmental Report Tracking System

ERTS # 670548

Initial Report

External Reference # See ERTS 542700

Caller Information

First Name JEFF
Last Name MORRIS
Business Name CORKY MORRIS LLC
Street Address
Other Address
City **State** WA **Zip**
E-mail JEFF@MORRISANDMORRIS.C **Confidential_FL** ☐
Phone (509) 991-1444 **Ext** **Type** Mobile

Where did it happen

Berth **Anchorage**
Location Name
Street Address 9802 MARTIN LUTHER KING JR WAY S
Other Address
City/Place SEATTLE **State** WA **Zip** 98118
County - Region KING **NWRO** **FS ID** 7163112
WIRA #
Waterway **Type**
Latitude **Longitude**
Topo Quad 1:24:000 SEATTLE
Direction/Landmark (mile post, cross roads, township/range)

What happened

Spills Program Oil Spill? N

Incident Date **Received Date** 2/4/2017 13:02
Medium SOIL
Material PETROLEUM - LUBE OIL
Quantity **Unit**
Source OTHER
Cause UNKNOWN
Activity UNKNOWN
Impact SOIL CONTAMINATION
Vessel Name
Hull Number

Primary Potentially Responsible Party Information

First Name **Last Name**
Name
Business Name CORKY MORRIS LLC
Street Address
Other Address
City **State** WA **Zip**
Phone **Ext** **Type**
E-mail

Additional Contact Information

Name **Phone** **Ext** **Type**

More Information

REPORT RECEIVED VIA EMAIL

From: Jeff Morris [mailto:jeff@morrisandmorris.com]
 Sent: Saturday, February 04, 2017 1:02 PM
 To: ECY DL NWRO ERTS <NWROERTS@ECY.WA.GOV>
 Subject: Corky Morris LLC

I am writing on behalf of Corky Morris LLC, the owner of property located at 9802 Martin Luther King Jr. Way S., Seattle, WA. A portion of the property had been used in the past for an auto wrecking yard. Recently we became aware of the existence of metals and petroleum in the soil and groundwater. At this point, we have not concluded whether the presence of these contaminants may present any threat to human health or the environment, but we are filing this report pursuant to MTCA. Additional investigatory work is being undertaken to determine the extent of the contamination. Thank you. Sincerely, Corky Morris LLC by Jeff Morris, Member

Corky Morris LLC
 Jeff Morris, Member
 jeff@morrisandmorris.com
 Mobile: (509)-991-1444
 Home: (509)-448-5600

Entry Person Kicken, Yvonne

Entry Date 2/8/2017

ERTS # 670548

Referral

Referral Method		Person Referred to MUSA TCP, DONNA	Referral # 219861
<input type="radio"/> E-mail ERTS number		Phone (425) 649-7136 Fax (425) 649-7098	Primary <input type="checkbox"/>
<input checked="" type="radio"/> E-mail attachment		E-mail DMUS461@ECY.WA.GOV	
<input type="radio"/> Print		Program/Organization TOXICS CLEANUP	
<input type="radio"/> Telephone		Address 3190 160th AVE SE	
		City Bellevue WA 98008-5452	
		Region/Location NWRO	
		Referral Date 2/8/2017	

Department of Ecology - Environmental Report Tracking System

ERTS # 670548

Followup

<u>Inspector Information</u>		<u>Where did it happen</u>		Followup #1
Referral # 219861		Berth		Anchorage
<input checked="" type="checkbox"/> Lead Inspector MUSA TCP, DONNA		Location Name		
Program/Organization TOXICS CLEANUP		Street Address 9802 MARTIN LUTHER KING JR WAY S		
* Region/Location NWRO		Other Address		
# of Ecology Staff 1	Overtime <input type="checkbox"/>	City/Place SEATTLE	State WA	Zip 98118-
		County KING	Region NWRO	FS ID 7163112
<u>Action</u>	Start Date 4/19/2017	End Date 4/19/2017	Waterway	Type
TCP - UPDATE FILE			WRIA #	
<u>What happened</u>	Spills Program Oil Spill? N	Latitude	Longitude	
Incident Date 2/4/2017		Topo Quad 1:24,000 SEATTLE		
<u>Medium</u>		Direction/Landmark (mile post, cross roads, township/range)		
SOIL				
<u>Material</u>				
PETROLEUM - LUBE OIL				
Quantity Unit	Est			
	<input type="checkbox"/>			
<u>Source</u>	Regulated? <input type="checkbox"/>	<u>Potentially Responsible Party Information</u>		
OTHER		Check if the primary PRP provided notice to Ecology <input type="checkbox"/>		
		Primary <input checked="" type="checkbox"/>	First	Last
		Name		
<u>Cause</u>		Business Name CORKY MORRIS LLC		
UNKNOWN		Street Address		
		Other Address		
		City	State WA	Zip
<u>Activity</u>		Phone	Ext	Type
UNKNOWN		E-mail		
<u>Impact</u>				
SOIL CONTAMINATION				
<u>Vessel</u>				
<div style="border: 1px solid black; padding: 5px;"> <p><u>Narrative</u></p> <p>Property is already listed on CSCSL and HSL, ranked a 5. See AFFORDABLE AUTO WRECKING TCP file. FSID 7163112 / CSID 1484. SHA is available through below link.</p> <p>Additional details available here: https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=1484</p> </div>				
Vessel Emergency <input type="checkbox"/>		Entry Person: MUSA TCP, DONNA		Entry Date 4/19/2017