



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Ave SE • Bellevue, WA 98008-5452 • 425-649-7000
711 for Washington Relay Service • Persons with a speech disability can call 877-833-6341

May 15, 2017

Ms. Eran Fields
Fields Holdings
2251 Linda Flora Dr
Los Angeles, CA 90129

RE: Site Hazard Assessment – Chevron 90129
Ecology FSID: 81966648 / CSID: 10632

Dear Ms. Fields:

The Washington State Department of Ecology (Ecology) will conduct a Site Hazard Assessment (SHA) for the following site:

Chevron 90129
4700 Brooklyn Ave NE
Seattle, WA 98105

This site has been on Ecology's Confirmed and Suspected Contaminated Sites List (CSCSL) since January 1990 for a reported release of petroleum products from a leaking underground storage tank.

SHAs are conducted under the Model Toxics Control Act (MTCA), Chapter 173-340-320 WAC. The purpose of an SHA is to gather information on past and present waste management activities and other basic site-specific environmental data to assess the site for its potential environmental hazard. Threats to human health and the environment are evaluated for potential contaminant exposure routes; resulting in a hazard ranking determination.

Sites are ranked on a scale of 1 to 5, with 1 representing the highest level of concern and 5 the lowest, relative to other ranked sites in the state. Ranked sites are placed on the state Hazardous Sites List (HSL). In some cases, the assessment may determine that no further action is warranted. In these cases, the site is not placed on the HSL and it is removed from Ecology's CSCSL.

Information contained in Ecology's Northwest Regional Office (NWRO) site files will be considered in evaluating and scoring this site. Ecology wants to use the most recent and accurate data.



May 15, 2017

Page 2

You are requested to submit any additional environmental information regarding this site by June 15, 2017 as follows:

Priscilla Tomlinson
Washington Department of Ecology
Northwest Regional Office
3190 160th Ave SE
Bellevue, WA 98008

Additional data could include the results of any environmental assessments or laboratory analyses that have not previously been submitted to Ecology. A copy of our Integrated Site Information System (ISIS) Site Data Summary Sheet is enclosed. You may review the contents of Ecology's file on your site by contacting Sally Perkins at (425) 649-7190 or sper461@ecy.wa.gov. Your active participation in the assessment and scoring process is important to ensure that the best data available are used for scoring.

We may contact you in the near future to arrange a suitable time for any field activities, as appropriate. Fact sheets describing SHAs, the Washington Ranking Method and the HSL are enclosed for your information. A copy of the final SHA report and the scoring results will be sent to you.

If you have any questions, contact Priscilla Tomlinson at (425) 649-7135 or priscilla.tomlinson@ecy.wa.gov.

Sincerely,



Donna Musa
NWRO Site Hazard Assessment Coordinator
Toxics Cleanup Program

By certified mail [9171 9690 0935 0106 7201 20]

Enclosures: 4

cc: Priscilla Tomlinson, Ecology NWRO
Dale Myers, Ecology NWRO

CS ID: 10632 Chevron 90129 FS ID: 81966648 [Site Page](#) [Site Docs](#) [Vicinity Map](#)

Alternate Names: CHEVRON 0129, CHEVRON SS 90129

LOCATION

Address: 4700 BROOKLYN AVE NE **Lat/Long:** 47.663351 -122.313945 **UST ID:** 5046
 SEATTLE 98105 **WRIA:** 8 **Legislative District:** 43
County: King **TRS:** 25N 4E 8 **Congressional District:** 7

DETAIL

Status: Cleanup Started **RANK:** **NFA Received?** No **NFA Date:**
Site Manager: Myers, Dale R **Statute:** MTCA **NFA Reason:**
Responsible Unit: Northwest **Has VCP/In VCP:** No/No **Has Institutional Control?** No **Is PSI Site?** No

CLEANUP UNITS

Unit ID	Cleanup Unit Name	Unit Status	Resp Unit	Unit Manager	Current Process
10324	Chevron 90129	Cleanup Started	NWRO	Myers, Dale R	Ecology-supervised or

AFFECTED MEDIA & CONTAMINANTS

CONTAMINANT	MEDIA					
	Soil	Ground Water	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Petroleum-Gasoline	C	C				

Key:
 B--Below Cleanup Level C--Confirmed Above Cleanup Level RA--Remediated-Above
 S--Suspected R--Remediated RB--Remediated-Below

SITE ACTIVITIES

Area	Activity	Status	Start Date	End Date	Activity Lead
LUST	LUST - Notification	Completed	1990-01-04	1990-01-04	
LUST	LUST - Report Received	Completed	1990-09-14	1990-09-14	
LUST	LUST - Report Received	Completed	1990-12-11	1990-12-11	
LUST	LUST - Report Received	Completed	1991-11-19	1991-11-19	
LUST	LUST - Report Received	Completed	1992-06-11	1992-06-11	
LUST	LUST - Report Received	Completed	1992-10-22	1992-10-22	
LUST	LUST - Report Received	Completed	1993-05-05	1993-05-05	
LUST	LUST - Report Received	Completed	1993-06-03	1993-06-03	
LUST	LUST - Report Received	Completed	1993-06-09	1993-06-09	
LUST	LUST - Report Received	Completed	1994-01-05	1994-01-05	
LUST	LUST - Report Received	Completed	1994-03-08	1994-03-08	
LUST	LUST - Report Received	Completed	1995-04-24	1995-04-24	
LUST	LUST - Report Received	Completed	1995-10-05	1995-10-05	
LUST	LUST - Report Received	Completed	1996-04-03	1996-04-03	
LUST	LUST - Report Received	Completed	1997-02-26	1997-02-26	
LUST	LUST - Report Received	Completed	1998-04-10	1998-04-10	
LUST	LUST - Report Received	Completed	1999-07-29	1999-07-29	
LUST	LUST - Report Received	Completed	2000-08-21	2000-08-21	
LUST	LUST - Report Received	Completed	2001-04-13	2001-04-13	
LUST	LUST - Report Received	Completed	2001-06-11	2001-06-11	
LUST	LUST - Report Received	Completed	2001-07-26	2001-07-26	
LUST	LUST - Report Received	Completed	2002-12-16	2002-12-16	
LUST	LUST - Report Received	Completed	2003-01-21	2003-01-21	
LUST	LUST - Report Received	Completed	2004-01-23	2004-01-23	
LUST	LUST - Report Received	Completed	2004-12-13	2004-12-13	
LUST	LUST - Report Received	Completed	2005-10-03	2005-10-03	
LUST	LUST - Report Received	Completed	2006-09-20	2006-09-20	
LUST	LUST - Report Received	Completed	2009-09-08	2009-09-08	
LUST	LUST - Report Received	Completed	2010-02-22	2010-02-22	
LUST	LUST - Report Received	Completed	2011-02-23	2011-02-23	
LUST	LUST - Report Received	Completed	2011-02-23	2011-02-23	
LUST	LUST - Report Received	Completed	2011-09-15	2011-09-15	
LUST	LUST - Report Received	Completed	2012-01-09	2012-01-09	
LUST	LUST - Site Assessment Report	Completed	2017-03-06	2017-03-06	
Admin	Site Hazard Assessment/Federal Site Inspection	Planned	2017-05-08	2017-08-15	Tomlinson, Priscilla