



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

June 23, 2017

TO: TCP File (CarMax 7250)

FROM: Donna Musa
Ecology NWRO Initial Investigations Coordinator

SUBJECT: Initial Investigation: No Further Action (NFA) Determination
CarMax 7250
21317 Hwy 99
Lynnwood, WA 98036
Parcel ID # 005807000000606
Facility Site ID: 9617
Cleanup Site ID: 13288

Effective May 17, 2017, Ecology has determined that no further action is necessary (at the Initial Investigation stage) due to independent remediation.

Snohomish Health District received evidence of cleanup:

Letter Reports for Testing and Inspection Services for: Limited Soil Sampling and Analysis
Proposed CarMax, Lynnwood, WA. Krazan & Associates, Inc.

- Spoils Pile Area, July 26, 2016.
- Northwest Section, August 29, 2016.
- Pond Area, September 23, 2016.

The above documentation provides sufficient evidence that this cleanup was conducted to MTCA Method A cleanup levels for unrestricted land use. Mike Young, Snohomish Health District, has recommended no further action at this site, and Ecology concurs.

Additional information about Snohomish Health District and Ecology's review of this site cleanup may be accessed here: <https://fortress.wa.gov/ecy/gsp/Sitepage.aspx?csid=13288>.

To view the documentation Ecology has available electronically, on the right-hand side of the page, click on [View Electronic Documents](#).