

INITIAL INVESTIGATION FIELD REPORT

ERTS # 626668 County Whatcom

Parcel # 3803190120190000 FS ID # 24778 / CSID 11734

SITE INFORM	ATION			
Site Name (e.g. FAMILY FOOT	, Co. name over door): CARE PS	Site Address (including (2000 BROADWAY, BE	Site Phone: () - () -	
Site Contact and MICHAEL SHE		Site Contact Address (inc Same as above	Site Contact Phone: (360) 738-9797	
Site Owner: Konstantino E (Gus)	E. Tsimouris	Site Owner Address (inc 318 Highland Dr Bellingham, WA 982)	25	Site Owner Phone: (360) 224-5242
Site Owner Con	tact (if any):	Site Owner Contact Addre	ess (including City and Zip+4) if any:	Owner Contact Phone:
Previous/Addition Swanson Ped	nal Site Owner(s): diatric Center	Previous/Additional Site (Owner(s) Address (including City and Zip+4):	Phone:
Alternate Site N	Names:	Comments:		Is property > 10 acres? Yes ☐ No ☒
	Location: Quarter-0	Quarter: Section:	19 Township: 38N Range: 3E	
	Latitude: N 48 c	legrees 45'41.4" (data	collected in the field)	
	Longitude: W 122	degrees 29'08.5"		
INSPECTION	INFORMATION			
Inspection Da	te: 08/09/2011 Time:	09:30 ⊠am □pm	Entry Notice: Announced ⊠ Unanr	nounced
Photographs?	Yes ⊠	No 🗌	Weather: Clear ⊠ Rain □ Temp	erature: ° F
Samples?	Yes 🗌	No 🗵	Wind Direction: calm Wind Speed:	
RECOMMENDA	TION			
No Further Acti	ion (due to):		ISIS ACTIONS (check all that apply):	
	nreatened release does i A or Non MTCA substan		Site Hazard Assessment (MTCA List) (0	CSCS List)
	r threatened release (Ne	ever contaminated)	LUST List	
Educational	-		(deleted RCU option)	
	gram/agency () cleanup action complete	ed (i.e., remediated)	Comments:	
Site assessm removal of a	500-gallon abandor	ned UST. Groundwate	oil (2,600mg/kg) from a sample collect r was not encountered.	ed during the
Recommend C	SCS list. Lube oil con		n): n place above MTCA at the boundary of th oil that extends beneath the property buildi	
Investigator: /	Audrey Heisey		Date Submit	ted: 08/09/2011

OBSERVATIONS

Description : Prope currently occupied	d by a	med	lical c	linic	(Fam	ily Fo	ot Ca	are). ˈ	The f	orme	r US	T loca							d
the remainder of t	he pr	opert	y is c	overe	ed wit	h bui	lding	foun	datio	n or a	aspha	alt.							
Adiaining proporti	oo ina	dudo:																	
Adjoining propertion East, an unnamed				e da	rage :	with a	allse	rd Oil	AST	is lo	cated	Liust	east	of the	suhi	ect n	roner	tv in t	the
same building as															Jubj	coi p	горсі	ty III I	uic
west, 2309 Broad											.00		,,,,,	,					
north, 2010 Broad																			
northwest, city par																			
and south, name	over o	door:	The	Foun	tain r	estau	rant.												
Description of past practices likely to be responsible for contamination:																			
ACTIVITIES OR PR	RACTI	CES	RESF	PONS	IBLE	FOR	CON	ГАМІ	NATIO	ON:									
Spill						П		LUST					\boxtimes						
Pesticide disposal																			
Landfill Improper handling																			
Drums																			
Other – Describe:																			
Are discharges permitted? (if yes, describe) No Standard Industrial Codes (if known):																			
						Yes	\sqcup												
CONTAMINANT(S)																		
AFFECTED		CON	ΓΑΜΙΝ	IANTS	(#1-1	9: See	conta	aminar	nts key	below	v) Ente	er lette	r desig	gnating	statu	s of co	ntami	nant:	
MEDIA		C = C	onfirm	ned (at	ove M	ITCA I	Metho	d A); S	S = Su:	specte	d; R =	Reme	ediated	d; B =	Below	MTCA	A Meth	od A	
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
Ground Water																			
Surface Water																			
Drinking Water																			
Soil								С											
Sediment																			
Air																			
1 Metals - Lead	1				8 No	on-Hal	Org:	Petro	Other	(Oil)			15		ı				
2 Non-Hal Org: Be	nzene									ecifie	d		16						
3 Non-Hal Org: MT							•	PAHs					17						
				11						18									
5 Non-Hal Org: Other Non-Hal Org (T/E/X) 12 19																			
6 Non-Hal Org: Petro Diesel 13																			
7 Non-Hal Org: Petro Gasoline				14															

SITE INFORMATION				
	atcom-Labounty complex	Slope 0-8 percent		
Site vegetation/cover prese	nt:			
Forest		Pasture/open field		
Bare soil		Wetlands		
Brush		Pavement	\boxtimes	
Landscaped		Surface water		
Other – Describe:				
Are there any drinking water s	ystems affected?		☐ Yes	⊠ No
Municipal, private, or both			_	_
How many people are est				
Is there a potential for a releas	e or threatened release to affect a	drinking water source?	☐ Yes	⊠ No
Are there monitoring wells in the	ne vicinity?		Yes	☐ No ⊠ Unk
Are there dry wells in the vicini	ty?		☐ Yes	☐ No ⊠ Unk
	<u> </u>			
CONTAMINANT PATHWAY	S AND TARGETS			
	Ingestion	Inhalation		Contact
Ground Water	П	П		П
Surface Water		П		
Drinking Water		П		
Soil	 ⊠			
Sediment				
Air				
Targets Possible:		Residential		
Human, adult	7	Industrial		
Human, children	_	Commercial		
	⊐ e WARM Scoring Manual for de		□□ If yes, des	cribe:
Constitue on vinorimento (Co	e with cooming mandarior de	inition). 🗀 165 🖂 146	11 yes, acc	oribe.
General Comments:				

SITE MAP/DIAGRAM

Site Name: See file report "Undergrou Washington" for a site map/diagram.	Storage Tank Site Assessment at Closure – 2000 Broadway, Bellingham,
↑ North	Approximate scale: inch = feet
ERTS Number	County
nspector	Date