

Department of Ecology-NWRO

Underground Storage Tank
Notice of Confirmed Release

Complaint received by 4/5/90 A. Petrie & Joe Hickey Date 10/31/90
Reporter name O'Sullivan Construction
address Follow-up call on 11/5/90 from owner Jim Campbell
phone no. _____

100221
Jnc#2057

Site name Rainier Beach Automobile site phone no. 723-0355
address 9479 Rainier Ave S.
city Seattle county _____ zip 98118

Site owner Jim Campbell owner's phone 722-9975
owner's address same as above
city _____ zip _____

Consultant company ENVIROS
name Mike Sutowick phone no. 820-7575

Other contact O'Sullivan Construction phone no. 682-2440
contact affiliation Joe Stemmerman

Description of Incident

Material	# Tanks	Status/Date
gasoline.....	<u>3</u>	<u>5000, 4000, 2000 gal</u>
diesel		
waste oil	<u>1</u>	<u>500 gal.</u>
heat fuel		
.....		
.....		
Total number tanks:	<u>4</u>	Cleanup Status <u>on-going</u>

guessed
20
gal

Comments Under the 2 gas tanks above cleanup
levels. Don't have copies of soil analysis,
still at lab, verbal only.
Has hired ENVIROS & O'Sullivan to do remediation.
Wants to landfarm in Snohomish Co. Has 6 acres
out there. I told him to contact county for any
permits. I will mail him guidance documents.

3/15/91
from
report

Some contaminated soil under bldg (south), near water main (north), edge of
fuel island canopy (east). No GW encountered. 30 cy landfarmed in
Snohomish Co. - no Enviro involvement - on Mr. Campbell's property. 30-40 cy
mixed with clean fill and used as backfill.

Date inspected _____ Investigator _____ Referred to _____