

MW-3

Dry Dock

Retaining Wall


**DRAFT**

MW-2

Former location of 10,000-gallon diesel UST.

MW-4

UST removal excavation.



Composite Sample OB1/OB2/OB3: 120 ppm

W-6  
<50

N-6  
(13,000)

B-N-12  
(24,000)

E-6  
<50

B-S-12  
(8,000)

S-6  
<50

MW-1

UST: Single-wall steel, approximately 8 foot diameter by 28 foot length. Approximately 300-gallons of residual fuel removed from tank. Tank moderately rusted and pitted, but no obvious holes. Owner reports past property with leaking turbine at north end of the tank.



Soil sample location. Concentrations of diesel are in parts per million (ppm). For reference the WDOE target compliance level for diesel in soil is 2,000 ppm.



### ENVIRONMENTAL ASSOCIATES, INC.

1380 112th Avenue N.E., Ste. 300  
Bellevue, Washington 98004



### SAMPLING PLAN

Lake Chelan Boat Company  
1418 West Woodin Avenue  
Chelan, Washington

Job Number:

JN-31174

Date:

November 2011

Scale:

Plate:

3

JN-31174 Lake Chelan Boat Company UST Removal Photos

