

Department of Ecology - Northwest Regional Office
 Underground Storage Tank Notice of Confirmed Case

Christi

Incident #: 5697 ^{Rev'd 4/19/95 CM}
 UST #: 102471 Date Ecology Notified: 12-20-94 (HQ) Received by: J. Hickey (from HQ)
 ERTS #: 19053 Incident Reported by: Chris Coldeen Phone: 567-4652

Site

Owner

Name: Coldeen Property Old Gas Station
 Address: 15631 Westside Hwy SW
 City: Vashon Is.
 Zip + 4: 98070 - 3719
 County: King
 Phone: _____
 Contact: _____

Name: _____
 Address: _____
 City: _____
 Zip + 4: _____
 County: _____
 Phone: _____
 Contact: _____

Consultant/Other Contacts

Contact Name	Affiliation	Phone	Ext.
<u>Dave Murdoch</u>	<u>TME Environmental</u>	<u>792-9741</u>	_____
_____	_____	_____	_____
_____	_____	_____	_____

Affected Media

☒ Soil ☐ GW ☐ DW ☐ SW ☐ Sed.

Free Product?

☐ Yes ☒ No ☐ Excavation? ☐ GW?

Tank Information

Tank ID	Substance	Status	Status Date	Tank ID	Substance	Status	Status Date
1.	<u>gasoline</u>	<u>removed</u>	<u>July 1994</u>	6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Cleanup Status: ☐ Assessing ☐ In Progress ☐ Monitoring ☒ Conducted ^{"Limited"} ☐ Unknown

Comments (include remediation methods, PCS status, and if this is a "limited" cleanup): 12 yds³ of PCS was removed. Contamination remains in the soil, but based on conversations w/ the persons involved, it is a small amount of soil (less than 10 yds³), and there was not groundwater encountered while digging. Rainwater did accumulate in the excavation, and has and will be properly disposed of, according to the owner.