

Monitoring Well

Groundwater Elevation Contour

Soil Boring

8.72 Groundwater Elevation (ft NAVD88)

Former Sears Service Center

7.64 Depth to Water from Top of Casing (ft)

Former UST Location

- 2. Casing elevations measured by David Evans and Associates on 2/14/2017.
- 3. Black and white reproduction of this color original may reduce its effectiveness and lead to incorrect interpretation.

Data Source: Google Earth Pro.



Nitze-Stagen Starbucks Center Area Seattle, Washington

Groundwater Contours August 2017

Figure

4