

2992

WILSON OIL, INC.

110 Panel Way — P.O. Box 69
Longview, Washington 98632
Phone 423-3300

RECEIVED

'92 FEB 14 P3:27

DEPARTMENT OF ECOLOGY
S W REGIONAL OFFICE

February 10, 1992

Pattie Martin
Department of Ecology
7272 Clearwater Lane LU-11
Olympia, WA 98504-6811

TOPIC: John's Shell, 1410 Ocean Beach Hwy., Longview, WA

Dear Pattie:

About 50 yards of soil from John's Shell had gasoline odor at the time of excavation in October, 1991. We have allowed this material to sit above ground under black plastic for three months.

I recently had Jeff Wilson of Cowlitz Clean Sweep take a soil sample. The results are attached, and are below minimums, as we discussed today by phone. Therefore, I am removing this soil and using it for fill dirt, and have completed our successful remediation of this site.

Very truly yours,



Steve Wilcox
President

COLUMBIA ANALYTICAL SERVICES, INC.

Analytical Report

Client: Wilcox & Flegel
Project: Wilcox Soil Pile/#1
Sample Matrix: Soil

Date Received: 01/13/92
Date Extracted: 01/17/92
Work Order #: K920226

BTEX
EPA Methods 5030/8020
mg/Kg (ppm)
Dry Weight Basis

Sample Name:
Lab Code:
Date Analyzed:

Soil Pile #1
K0226-1
01/18/92

Method Blank
K0226-MB
01/18/92

Analyte	MRL		
Benzene	0.05	ND	ND
Toluene	0.05	ND	ND
Ethylbenzene	0.05	0.08	ND
Total Xylenes	0.05	0.19	ND

MRL Method Reporting Limit

ND None Detected at or above the method reporting limit

Approved by Cheri Elliott Date 1/31/92

00001