

Department of Ecology - Northwest Region Office
 Underground Storage Tank Notice of Confirmation Release

Incident #: 5472 Date Ecology Notified: 10/6/94 Received by: Dorothy Glenn
 UST #: 000892 Incident Reported by: Donna Hewitt Phone: 632-3123
 ERTS #: 17401 DLH Environmental

Site

Owner

Name: Morse
Morris Const. Group
 Address: 5500 S. 1st St.
 City: Everett, WA 98203
 Zip + 4: _____
 County: _____
 Phone: 258-2731
 Contact: Lloyd Archabald

Name: Same
 Address: _____
 City: _____
 Zip + 4: _____
 County: _____
 Phone: _____
 Contact: _____

Consultant/Other Contacts

Contact Name	Affiliation	Phone	Ext.
<u>Donna Hewitt</u>	<u>DLH Enviro.</u>	<u>623-3123</u>	_____
_____	_____	_____	_____
_____	_____	_____	_____

Affected Media

☒ Soil ☐ GW ☐ DW ☐ SW ☐ Sed.

Free Product?

☐ Yes ☐ No ☐ Excavation? ☐ GW?

Tank Information

Tank ID	Substance	Status	Status Date	Tank ID	Substance	Status	Status Date
1.	<u>Diesel gas</u>			6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Cleanup Status: ☐ Assessing ☒ In Progress ☐ Monitoring ☐ Conducted ☐ Unknown

Comments (include remediation methods, PCS status, and if this is a "limited" cleanup):

Were removing a gasoline tank, and discovered
diesel contamination. The source could be from
off site. Highest sample was 420 ppm. They
excavated the contaminated soil, stockpiled, and
will clean on site.