

Mr. Eric Hetrick Chevron Environmental Management Company 6101 Bollinger Canyon Road San Ramon, California 94583

Subject:

**Well Abandonment Memo** 

**Chevron Service Station No. 95311** 

Facility/Site ID No.:25489377

1018 Plum Street Olympia, Washington

Dear Mr. Hetrick:

The purpose of this letter is to report on the decommissioning of five groundwater monitoring wells (MW-1 through MW-5) at the referenced site.

On August 7, 2018, a representative of Leidos Inc. (Leidos), was present at the site to oversee the decommissioning process, which was performed by Cascade Drilling of Woodinville, Washington.

The wells were filled in place with bentonite in accordance with applicable Washington State codes and regulations for the decommissioning of resource protection wells (WAC 173-160). Well boxes were left in place and filled with concrete to grade.

If you have any questions or comments, please contact me at (425) 482-3328 or via email at ottemanr@leidos.com.

Sincerely,

Leidos Inc.

Ruth Otteman

Project Manager, LG #2633

**Enclosures:** 

Figure 1 – Site Map

cc: Mr. Satnam Singh, MJMG Group LLC (hard copy & email)

9639 Summerfield Ct SE, Olympia, WA 98513

satnamtmobile@gmail.com

Ms. Carol Johnston, Washington State Department of Ecology, (hard copy & email)
Southwest Regional Office, Toxics Cleanup Program
300 Desmond Drive, Lacey WA 98503-1274
cjon461@ecy.wa.gov

Project File

## REPORT LIMITATIONS


This technical document was prepared on behalf of CEMC and is intended for its sole use and for use by the local, state or federal regulatory agency that the technical document was sent to by Leidos. Any other person or entity obtaining, using, or relying on this technical document hereby acknowledges that they do so at their own risk, and that Leidos shall have no responsibility or liability for the consequences thereof.

Site history and background information provided in this technical document are based on sources that may include interviews with environmental regulatory agencies and property management personnel and a review of acquired environmental regulatory agency documents and property information obtained from CEMC and others. Leidos has not made, nor has it been asked to make, any independent investigation concerning the accuracy, reliability, or completeness of such information beyond that described in this technical document.

Recognizing reasonable limits of time and cost, this technical document cannot wholly eliminate uncertainty regarding the vertical and lateral extent of impacted environmental media.

Opinions and recommendations presented in this technical document apply only to site conditions and features as they existed at the time of Leidos site visits or site work and cannot be applied to conditions and features of which Leidos is unaware and has not had the opportunity to evaluate.

All sources of information on which Leidos has relied in making its conclusions (including direct field observations) are identified by reference in this technical document or in appendices attached to this technical document. Any information not listed by reference or in appendices has not been evaluated or relied upon by Leidos in the context of this technical document. The conclusions, therefore, represent our professional opinion based on the identified sources of information.





Legend

Abandoned Monitoring Well Location

— – – Property Boundary

Chevron Service Station No. 95311 1018 Plum Street Olympia, Washington Figure 1 Site Map

DATE: 8/8/2018 DRAWING: 9-5311\_Siteplan 2010.dwg

leidos