



# Parker Paint

Mfg. Co., Inc.

3326 South Junett • Tacoma, WA 98409

(206) 473-1122

FEBRUARY 3, 1992

'92 FEB -5 10:41

Tom Todd  
Department of Ecology  
Southwest Regional Office  
7272 Cleanwater Lane, LU-11  
Olympia, Wa. 98504-6811

DEPARTMENT OF ECOLOGY  
S W REGIONAL OFFICE

Parker Paint is in the process of removing 11 underground storage tanks at its' factory. On Friday, January 31, 1992 test results from samples taken by Hart/Crowser established a contamination problem under one of the tanks.

The suspected contamination appeared under the S-62 (Texanol) tank and is being retested to establish exact levels of product in the soil. This tank was tested for leaking in 1990 and found to be tight.

The entire excavation has been covered with plastic and further test results are due February 4, 1992 from Hart/Crowser. As results and progress are available I will continue to keep you updated.

Ron Wade  
Man./Dist. Mgr.  
Parker Paint

RW/ce