

TBT Bioaccumulation Testing Sampling Location Plan Cap Sante Marina



- DMMUs INCLUDED IN BIOACCUMULATION TEST SAMPLE COMP 1
- DMMUs INCLUDED IN BIOACCUMULATION TEST SAMPLE COMP 2
- 1 SURFACE DMMU DESIGNATION
- CONFIRMED SAMPLE LOCATION AND NUMBER
- PROPOSED LOCATION NOT SAMPLED
- FOUND C.O.E. BRASS CAP MONUMENTS.
- FOUND PREVIOUS SURVEY CONTROL POINTS
- SET 2" AL CAP ON #5 REBAR
- SET PN&D NAIL WITH SHINER
- WOOD PILE
- WOOD PILE WAVE BARRIER
- CULVERT LOCATION

Note: Base map prepared from drawing provided by Pertovich, Nottingham & Drage, Inc. entitled "Plan View", dated September 7, 1998.