

## **Appendix A**

### **Photo Documentation**

# Blaine Remedial Excavation Report

## Appendix A



Excavation 2 prior to decommissioning of service station and remedial excavation (April 26, 2011)



Excavation 1 prior to remedial excavation (April 26, 2011)



# Blaine Remedial Excavation Report

## Appendix A



Asphalt removal at Excavation 1 (April 26, 2011)



Temporary storage of contaminated soil from Excavation 1 (April 26, 2011)



# Blaine Remedial Excavation Report

## Appendix A



Station Decommissioning, flushing the product lines (April 26, 2011)



Decommissioning of the fuel dispensers (April 26, 2011)



# Blaine Remedial Excavation Report

## Appendix A



Final boundary of Excavation 1 (April 27, 2011)



Removal of fuel dispenser concrete footing (April 27, 2011)



# Blaine Remedial Excavation Report

## Appendix A



**Backfilling of Excavation 1 (April 29, 2011)**



**Compaction of Excavation 1 (April 29, 2011)**



# Blaine Remedial Excavation Report

## Appendix A



Excavation 1 completed (April 29, 2011)



Removal of the canopy (April 29, 2011)



# Blaine Remedial Excavation Report

## Appendix A



**Beginning of Excavation 2 (May 3, 2011)**



**Continuation of Excavation 2 (May 3, 2011)**



# Blaine Remedial Excavation Report

## Appendix A



ESN NW mobile laboratory



Transporting contaminated soil to disposal facility



# Blaine Remedial Excavation Report

## Appendix A



Slot cut excavation technique at Excavation 2 (May 4, 2011)



Removal of groundwater at the base of Excavation 2 (May 5, 2011)



# Blaine Remedial Excavation Report

## Appendix A



Groundwater treatment and holding tanks



Application of EHC-O (May 6, 2011)



# Blaine Remedial Excavation Report

## Appendix A



Backfilling northwest corner of Excavation 1 (May 6, 2011)



Contaminated area in the vicinity of decommissioned groundwater monitoring well MW-2



# Blaine Remedial Excavation Report

## Appendix A



Continual excavating and backfilling at Excavation 2



Backfilling and compaction at Excavation 2 (May 17, 2011)



# Blaine Remedial Excavation Report

## Appendix A



**ECHO application (May 17, 2011)**



**Excavation 2 compacted and backfilled to grade (May 25, 2011)**