

STATE OF WASHINGTON DEPARTMENT OF ECOLOGY

1250 W Alder St • Union Gap, WA 98903-0009 • (509) 575-2490

July 30, 2019

Jim Cach Coleman Oil Company 529 E. Kennewick Avenue Kennewick, WA 99336

Re: Completion of Remedial Investigation Stage of Site Work

• Site Name:

Coleman Oil Biodiesel Spill

• Site Address:

3 E. Chehalis Street, Wenatchee

• Facility Site ID:

83844381

• Cleanup Site ID No.:

13215

• Agreed Order No.:

DE 15389

Dear Jim Cach:

The Department of Ecology (Ecology) has received the report titled "SRI Addendum – Sediment Characterization Report," prepared by HydroCon, dated May 22, 2019 and revised July 17, 2019. Ecology hereby approves that document, pending public review and comment.

With the completion of the "SRI Addendum – Sediment Characterization Report," Ecology considers the Remedial Investigation (RI) stage of the site work to be complete, pending public review and comment.

The following are the documents that comprise the RI Report in entirety, and will all be included during the public review period for the RI.

- "Supplemental Remedial Investigation Report, prepared by HydroCon," dated August 8, 2018, and revised December 4, 2018.
- "SRI Addendum Uplands Soil Characterization Report," prepared by HydroCon, dated March 6, 2019.
- "Quarterly Groundwater Monitoring Report March 2019," prepared by HydroCon, dated May 28, 2019.
- "SRI Addendum Sediment Characterization Report," prepared by HydroCon, dated May 21, 2019 and revised July 17, 2019.

R

Jim Cach Coleman Oil Company July 30, 2019 Page 2

We have reviewed hard copies within our file and request the following additional unbound hard copies so that we have a sufficient number of copies for both our file record and public review:

- Two color hard copies of the SRI Report Text, Figures, and Tables revised December 4, 2018, with appropriate figures in 11" x 17" format.
- One hard copy of the SRI Report Appendices revised December 4, 2018
- One color hard copy of the SRI Addendum Uplands Soil Characterization Report dated May 28, 2019.

Consistent with Agreed Order DE 15389, the next major deliverable for the Site, the Draft Feasibility Study (FS) Report, will be due 90 days after the date of this letter, unless significant public comments on the RI are received by Ecology. If significant public comments on the RI are received, then the due date of the Draft FS Report may be adjusted by Ecology.

We appreciate the Coleman Oil Company and team's efforts toward cleaning up this site.

Please feel free to call me at (509) 454-7835 or email me at frank.winslow@ecy.wa.gov with any questions.

Sincerely yours,

Frank P. Winslow

Cleanup Site Manager

Toxics Cleanup Program, Central Region Office

cc:

Patrick Wicks, EEC

Craig Hultgren, HydroCon

Fur four