

Department of Ecology - Northwest Regional Office
Underground Storage Tank Notice of Confirmation Release

Incident #: 4596 Date Ecology Notified: 8-19-93 Received by: J Brails
UST #: 012765 Incident Reported by: S SPENCER-ROTH Phone: 206 7475618
ERTS #: _____

Site		Owner	
Name:	<u>"GASCO" (FORMER) SERVICE STATION</u>	Name:	<u>JIM & MARY DEVANEY</u>
Address:	<u>14805 INTERURBAN AVE S</u>	Address:	<u>1000 AUBURN WAY S</u>
City:	<u>TUKWILA</u>	City:	<u>AUBURN, WA</u>
Zip + 4:	<u>98168-4619</u>	Zip + 4:	<u>98002</u>
County:	<u>KING</u>	County:	_____
Phone:	<u>NA</u>	Phone:	_____
Contact:	<u>NA</u>	Contact:	_____

Consultant/Other Contacts

Contact Name

Affiliation

Phone

Ext.

SHANNAN SPENCER-ROTH GEOTECH 206 285-0356

Affected Media

☒ Soil ☐ GW ☐ DW ☐ SW ☐ Sed.

Free Product?

☐ Yes ☒ No ☐ Excavation? ☐ GW?

Tank Information

Tank ID	Substance	Status	Status Date	Tank ID	Substance	Status	Status Date
1.				6.			
2.				7.			
3.				8.			
4.				9.			
5.				10.			

Cleanup Status: ☐ Assessing ☐ In Progress ☐ Monitoring ☒ Conducted ☐ Unknown

Comments (include remediation methods, PCS status, and if this is a "limited" cleanup): REVIEWED RPT 8-24-93

LIMITED CLEANUP. EXCAVATED 700 YDS SOIL. UNABLE TO PROCEED
EAST BECAUSE OF STREET RIGHT-OF-WAY & UTILITIES INTERFERENCE.
CONCENTRATIONS OF GASOLINE RANGE HYDROCARBONS AT EAST WALL: ~
100 PPM. TANKS ON UST SITE 012765 ARE CODED "C" - CLOSED IN PLACE.
TANKS ARE NOT IN GROUND TANKS WERE REMOVED IN THE 80'S.