

**WORKSHEET 1  
SUMMARY SCORE SHEET**

**Note:** This document currently has no provision for sediment route scoring.

Site Name/Location (City, County, Section/Township/Range):

Maltby Warehouse and Field Site, 7414 W. Bostian Rd., Woodinville,  
Snohomish, 26/27N/5E.

Site Description (Include management areas, compounds of concern, and quantities):

Maltby Warehouse and Field site located at 7414 West Bostian Rd, Woodinville was used as a drum storage depot during the years 1970 -1972. The Ecology and Environment, Inc, site inspection file indicates that the site was reportedly used as a drum reconditioning operation. An interview with the former owner during that time period indicates that no drum cleaning or reconditioning was conducted at the site.

Since that time much of the topsoil has been scraped from the area and stockpiled on the west side of the property. A site hazard assessment of the site was conducted on November 29, 1993. There was a large pile (unknown quantity) of soil on the north west side of the property. Two soil samples were collected from the pile area, one directly from the pile and the second sample taken from sediments in a drainage ditch on the northwest side of the pile. The pile from the sediments showed levels of TPH Gasoline just slightly above MTCA cleanup levels. The priority pollutant metals analysis from both sites did not exceed MTCA cleanup levels.

Special Considerations (Include limitations in site file data or data which cannot be accommodated in the model, but which are important in evaluating the risk associated with the site, or any other factor(s) over-riding a decision of no further action for the site):

**ROUTE SCORES:**

Surface Water/Human Health: NS

Surface Water/Environ.: NS

Air/Human Health: NS

Air/Environmental: NS

Ground Water/Human Health: NS

**OVERALL RANK: NFA**

Rev. 4/3/92