



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

August 11, 2010

Mr. Patrick Abe
7th Avenue Service
701 S Jackson
Seattle, WA 98104-3011

RE: Complaint Follow-up Site Visit at 7th Avenue Service on August 3, 2010

Dear Mr. Abe:

Thank you for your time during the site visit on August 3. The purpose of the site visit was to follow up on a complaint reported to the Department of Ecology. The complaint report was that a large number of drums of unknown origin were deteriorating in the parking lot and that they had been there for a long time.

Based on our discussion during the site visit, it is my understanding that the drums are investigation wastes from a site assessment done by contractors working for the property owner, Mr. Barry Mar. I will send Mr. Mar a separate letter about removing the drums.

While we were on site, we also evaluated the facility's level of compliance with the Washington State Dangerous Waste Regulations (Chapter 173-303 WAC). These regulations establish a system for safe and responsible management of dangerous waste. Based on my visit, it appears that 7th Avenue Service is regulated as a small quantity generator and that dangerous waste compliance issues have been well addressed at your site.

I did observe one area of non-compliance with the Dangerous Waste Regulations:

- Used Oil: The used oil tank must be marked with the words "Used Oil". Also, please be sure that nothing other than used oil is placed into the tank. The flyer we gave you during the site visit has guidelines for what can and cannot be disposed of as used oil.

In addition, there were two concerns that I would like to bring to your attention:

- It is the responsibility of site operators (or business owners) to ensure that no solid or liquid wastes are migrating offsite into stormwater conveyances such as the trench and storm drain paralleling 7th Avenue. Activities such as routine sweeping and immediate clean up of minor spills should be established at your site.




Mr. Patrick Abe
August 11, 2010
Page 2 of 2

- Tires should be stored inside or tarped to prevent possible toxic runoff into the stormwater system and stagnant water buildup within the tires - a known breeding ground for pests.

Please do not hesitate to contact me at (425) 649-7289 or trudy.harding@ecy.wa.gov if you have any questions.

Sincerely,



Trudy Harding, Compliance Inspector
Hazardous Waste and Toxics Reduction Program

TH:SA

Enclosure

By certified mail: 7009 2820 0001 7154 7144

cc: Eric Autry, Seattle Public Utilities
Barry Mar, Property Owner
Central Records

U.S. Postal Service™

CERTIFIED MAIL™ RECEIPT

(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com®

OFFICIAL USE

Postage	\$	
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Rest (Endo)		
Total		
Sent	PATRICK ABE	
Street or PO	7TH AVENUE SERVICE, LLC	
City, State, ZIP+4	701 S JACKSON SEATTLE WA 98104-3011	

Postmark Here

Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail.
- Certified Mail is *not* available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a *Return Receipt* may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "*Restricted Delivery*".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry.

PS Form 3800, August 2006 (Reverse) PSN 7530-02-000-9047

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

PATRICK ABE
 7TH AVENUE SERVICE, LLC
 701 S JACKSON
 SEATTLE WA 98104-3011

2. Article Number

(Transfer from service label)

7009 2820 0001 7154 7144

COMPLETE THIS SECTION ON DELIVERY

A. Signature

Simon

- Agent
- Addressee

B. Received by (Printed Name)

SIMON

C. Date of Delivery

8-12-10

D. Is delivery address different from item 1? Yes

If YES, enter delivery address below: No



3. Service Type

- Certified Mail
- Registered
- Insured Mail
- Express Mail
- Return Receipt for Merchandise
- C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes


UNITED STATES POSTAL SERVICE



First-Class Mail
 Postage & Fees Paid
 USPS
 Permit No. G-10

• Sender: Please print your name, address, and ZIP+4 in this box •

Department of Ecology
 Northwest Regional Office
 3190 - 160th Avenue S.E.
 Bellevue, WA 98008-5452





STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

August 11, 2010

Mr. Barry Mar
Property Owner
PO Box 3343
Seattle, WA 98114-3343

RE: Complaint Follow-up Site Visit at 7th Avenue Service on August 3, 2010

Dear Mr. Mar:

On August 3, 2010, I visited 7th Avenue Service at 701 S Jackson in Seattle to follow-up on a complaint reported to the Department of Ecology. The complaint reported was that a large number of drums of unknown origin were deteriorating in the parking lot and that they had been there for a long time.

Based on my discussion with the owner of 7th Avenue Service, Mr. Patrick Abe, it is my understanding that the drums are investigation wastes from a site assessment done by contractors working for you.

A part of our site visit was to evaluate the facility's level of compliance with the Washington State Dangerous Waste Regulations (Chapter 173-303 WAC). These regulations establish a system for safe and responsible management of dangerous waste. The concern we have about the drums of waste is that they may pose a threat to human health and the environment. If any of these drummed wastes designate as dangerous waste, they will need to be accumulated and disposed of properly.

You must complete the actions below within 30 days of receipt of this letter and send the required documentation within 45 days of receipt of this letter to the address above.

Failure to comply with these requirements within 30 days of the date of receipt of this letter could result in an administrative order and/or a penalty of up to \$10,000 per day for each violation.

Required Actions:

1. Label drums appropriately as "hazardous waste", "regulated solid waste" or as "waste pending analysis". Label with an accumulation start date.
2. Designate and dispose of dangerous waste accumulated in containers. Designate all residues and cleanup waste as required in WAC 173-303-070, and properly dispose of them. Provide




Mr. Patrick Abe
August 11, 2010
Page 2 of 2

copies of shipping documents or destination facility receipts (manifests, bills of lading) for any material managed off-site.

3. Designate any wash water generated during the investigation as required in WAC 173-303-070 and properly dispose of it. Obtain authorization before discharging wash water to the sanitary sewer. Provide copies of shipping documents or destination facility receipts (manifests, bills of lading) for any material managed off-site.

Please do not hesitate to contact me at (425) 649-7289 or trudy.harding@ecy.wa.gov if you have any questions.

Sincerely,



Trudy Harding, Compliance Inspector
Hazardous Waste and Toxics Reduction Program

TH: SA

Enclosure

By certified mail: 7009 2820 0001 7154 7137

cc: Eric Autry, Seattle Public Utilities
Patrick Abe, Business Owner
Central Records

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
 (Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com®

OFFICIAL USE

U
S
P
S
P
O
S
T
A
L
S
E
R
V
I
C
E

Postage	\$	Postmark Here
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement)		
Total Postage		
Sent To	BARRY MAR	
Street, Apt or PO Box	DOTT MAR, INC	
City, State,	PO BOX 3343	
	SEATTLE WA 98114-3343	

Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®.
- Certified Mail is *not* available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a *Return Receipt* may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS® postmark on your Certified Mail receipt is required.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "*Restricted Delivery*".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry.

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits. *HWTB. TH*

1. Article Addressed to:

BARRY MAR
 DOTT MAR, INC
 PO BOX 3343
 SEATTLE WA 98114-3343

COMPLETE THIS SECTION ON DELIVERY

A. Signature
 X *[Signature]* Agent Addressee

B. Received by (*Printed Name*) *BARRY MAR* C. Date of Delivery

D. Is delivery address different from item 1? Yes No
 If YES, enter delivery address below:



3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (*Extra Fee*) Yes

2. Article Number (Transfer from service label) **7009 2820 0001 7154 7137**

UNITED STATES POSTAL SERVICE


SEATTLE WA 981

16 AUG 2010 PM 8 T

First-Class Mail
 Postage & Fees Paid
 USPS
 Permit No. G-10

• Sender: Please print your name, address, and ZIP+4 in this box •

Department of Ecology
 Northwest Regional Office
 3190 - 160th Avenue S.E.
 Bellevue, WA 98008-5452



ERTS # 620637

Initial Report

External Reference #

Caller Information

First Name ERIC
 Last Name AUTRY
 Business Name SEATTLE PUBLIC UTILITIES
 Street Address 700 5TH AVE SUITE 4900
 Other Address
 City SEATTLE State WA Zip 98124-4018
 E-mail
 Phone (206) 954-4379 Ext Type Business
 Confidential_FL

Where did it happen

Berth
 Location Name
 Street Address 701 S JACKSON
 Other Address
 City/Place SEATTLE State WA Zip
 County - Region KING NWRO FS ID
 WIRA #
 Waterway Type
 Latitude Longitude
 Topo Quad 1:24:000 SEATTLE
 Direction/Landmark (mile post, cross roads, township/range)

What happened

Spills Program Oil Spill? N

Incident Date 6/7/2010 Received Date 6/17/2010 16:10
 Medium OTHER
 Material OTHER - SEE NOTE
 Quantity Unit
 Source INDUSTRIAL FACILITY
 Cause HUMAN FACTOR - FAILURE TO READ or FOLLOW
 Incident Type
 Activity STORING
 Impact POTENTIAL POLLUTION/RELEASE
 Vessel Name
 Hull Number

Primary Potentially Responsible Party Information

First Name PATRICK Last Name ABE
 Business Name 7TH AVE SERVICE, LLC
 Street Address 701 S JACKSON
 Other Address
 City SEATTLE State WA Zip
 Phone (206) 622-6511 Ext Type Business
 E-mail

Additional Contact Information

Name Phone Ext Type

More Information

REPORT RECEIVED VIA ONLINE SUBMITTAL FORM:

SPU conducted a source control inspection of this business. It was determined that the business routinely drains antifreeze to the ground where it is then discharged to the combined sewer system. SPU has issued a corrective action letter for this violation of the City's side sewer code. In addition to the above violation the site has a large amount of drums of unknown origin that are deteriorating in the parking lot and have been there for a long time. SPU did suggest that the drums be classified and properly disposed of however our authority is limited in areas that are out of the stormwater system. Please refer this site to Hazardous Waste. Please contact Eric for more information or a copy of the corrective action letter.

Entry Person SACAYANAN, TAMARA

Entry Date 6/18/2010

ERTS # 620637

Referral

<p>Referral Method</p> <p><input type="radio"/> E-mail ERTS number</p> <p><input checked="" type="radio"/> E-mail attachment</p> <p><input type="radio"/> Print</p> <p><input type="radio"/> Telephone</p>	<p>Person Referred to URBAN WATERS INITIATIVE NWRO WQ, BOB</p> <p>Phone (425) 649-7060 Fax (425) 649-7098</p> <p>E-mail rowr461@ecy.wa.gov</p> <p>Program/Organization WATER QUALITY</p> <p>Address</p> <p>City BELLEVUE WA 98008-</p> <p>Region/Location NWRO</p> <p>Referral Date 8/9/2010</p>	<p>Referral # 134586</p> <p>Primary <input type="checkbox"/></p>
<p>Referral Method</p> <p><input type="radio"/> E-mail ERTS number</p> <p><input checked="" type="radio"/> E-mail attachment</p> <p><input type="radio"/> Print</p> <p><input type="radio"/> Telephone</p>	<p>Person Referred to SEATTLE PUBLIC UTIL WQ, ERIC AUTRY</p> <p>Phone (206) 684-7988 Fax</p> <p>E-mail Email Seattle WQ</p> <p>Program/Organization SEATTLE</p> <p>Address Dexter Horton Bldg 710 2nd Ave Room 505</p> <p>City Seattle WA 98104</p> <p>Region/Location PUBLIC UTILITIES</p> <p>Referral Date 6/18/2010</p>	<p>Referral # 134587</p> <p>Primary <input type="checkbox"/></p>
<p>Referral Method</p> <p><input type="radio"/> E-mail ERTS number</p> <p><input checked="" type="radio"/> E-mail attachment</p> <p><input type="radio"/> Print</p> <p><input type="radio"/> Telephone</p>	<p>Person Referred to HARDING, TRUDY</p> <p>Phone (425) 649-7289 Fax</p> <p>E-mail THAR461@ECY.WA.GOV</p> <p>Program/Organization HAZARDOUS WASTE and TOXICS REDUCTION</p> <p>Address</p> <p>City WA</p> <p>Region/Location NWRO</p> <p>Referral Date 8/9/2010</p>	<p>Referral # 136118</p> <p>Primary <input checked="" type="checkbox"/></p>

ERTS # 620637

Followup

Inspector Information		Where did it happen		Followup #1
Referral # 136118		Berth	Anchorage	
<input checked="" type="checkbox"/> Lead Inspector HARDING, TRUDY		Location Name	7TH AVE SERVICE, LLC	
Program/Organization HAZARDOUS WASTE and TOXICS REDUCTION		Street Address	701 S JACKSON	
* Region/Location NWRO		Other Address		
# of Ecology Staff 2	Overtime <input type="checkbox"/>	City/Place SEATTLE	State WA	Zip
Action	Start Date	End Date	County KING	Region NWRO FS ID
FIELD RESPONSE - INVESTIGATION	8/3/2010	8/3/2010	Waterway	Type
			WRIA #	
What happened	Spills Program Oil Spill? N	Latitude	Longitude	
Incident Date 6/7/2010		Topo Quad 1:24,000 SEATTLE	Direction/Landmark (mile post, cross roads, township/range)	
<u>Medium</u>				
INDUSTRIAL PROPERTY				
<u>Material</u>				
PETROLEUM - WASTE/USED OIL				
Quantity Unit	Est			
	<input type="checkbox"/>			
<u>Source</u>	Regulated? <input type="checkbox"/>	Potentially Responsible Party Information		
INDUSTRIAL FACILITY		Check if the primary PRP provided notice to Ecology <input type="checkbox"/>		
<u>Cause</u>		Primary <input checked="" type="checkbox"/>	First	Last
HUMAN FACTOR - IMPROPER PROCEDURES		Name PATRICK	ABE	
<u>Incident Type</u>		Business Name	7TH AVE SERVICE, LLC	
		Street Address	701 S JACKSON	
<u>Activity</u>		Other Address		
STORING		City SEATTLE	State WA	Zip
<u>Impact</u>		Phone (206) 622-6511	Ext	Type Business
POTENTIAL POLLUTION/RELEASE		E-mail		
<u>Vessel</u>				

Narrative

On August 3, 2010, Warren Walton and I (Trudy Harding) went to the property on S. Jackson St. to look at the drums Mr. Autry spoke about in his initial ERTS call. We found twelve unlabeled, full drums and two empties located in a false alley parallel to Jackson St and Mr. Warren numbered those drums. We noted this site is an old gas station but no longer dispenses gas but does do vehicle servicing (LOFs) and some minor repairs. There was also a For Sale sign on the top of the building.

The operator of the site, Patrick Abe, said the drums had been there for about two years. They were generated through a site assessment and contained soil borings. Mr. Abe did not know if the analytical results indicated if any contained hazardous wastes. Mr. Abe gave us the land owner's name and phone number so we could follow up with him.

Additionally, Mr. Abe showed us a trench leading into a storm drain that Mr. Autry had wanted cleaned out. We took a picture of this for Mr. Autry's convenience as he was not able to meet us. Later, on 8/4/10, I talked with Mr. Autry and he said that he had also gone later and saw that everything he asked Mr. Abe to do was done.

We toured the site and asked Mr. Abe various questions about dangerous management as his facility. He told us that Emerald Services has been contracted to dispose of Used Oil and antifreeze. He uses up aerosol can products since they are expensive. We suggested the tire piles be moved inside or covered. The Used Oil tank should be marked as such. Mr. Walton gave him a pamphlet about fluorescent tube and electronics disposal.

The Compliance Unit will be sending a letter to Mr. Abe with the corrections he must make. Another will be sent to the landowner:

Barry Mar 206 623-3732
 DOTT MAR, INC
 PO Box 3343
 Seattle, WA 98114-3343 asking for analytical results, directing him to label the drums, and arranging for them to be shipped offsite.

These letters and a photo log will be available in Central Records by the end of the month. A photo log can also be viewed on the X drive, NWRO ERTS Additional Information

ERTS # 620637

Entry Person: HARDING, TRUDY

Entry Date 8/9/2010


7th Ave: wine LLC
701 S JACKSON
Seattle

8/3/10

ERTS 620637

WW - photos
TH - lead

JACKSON



ERTS – Internal Site Visit Report

SITE INFO

ERTS # 620637	Facility or Site name 7th Avenue Service, LLC	Date of site visit August 3, 2010
RCRA Site ID # None	Site address 701 S. Jackson Street Seattle WA 98104-3011	Site website
Site phone # 206 622-6511	Site contact Patrick Abe	Site contact e-mail

ECOLOGY INFO

Lead inspector Trudy A. Harding	Other representatives Warren Walton
Lead phone # 425 649 7289	Report written by Trudy Harding
Lead e-mail trudy.harding@ecy.wa.gov	Date report mailed August 11, 2010

INSPECTION REPORT

ERTS Complaint:

REPORT RECEIVED VIA ONLINE SUBMITTAL FORM:

SPU conducted a source control inspection of this business. It was determined that the business routinely drains antifreeze to the ground where it is then discharged to the combined sewer system. SPU has issued a corrective action letter for this violation of the City's side sewer code. In addition to the above violation the site has a large amount of drums of unknown origin that are deteriorating in the parking lot and have been there for a long time. SPU did suggest that the drums be classified and properly disposed of however our authority is limited in areas that are out of the stormwater system. Please refer this site to Hazardous Waste. Please contact Eric for more information or a copy of the corrective action letter.

Facility Background:

The facility is located in the International District of Seattle at the intersection of 7th and Jackson Streets. The building has been there since 1941 and was used as a gas station. Mr. Abe, the current operator of the site, has been there since 1972. The site no longer dispenses gas but does generate vehicle fluid waste such as used oil, antifreeze, and small amounts of brake fluid.

Facility Tour and Findings:

On August 3, 2010, Warren Walton and I (Trudy Harding) went to the property on S. Jackson St. to look at the drums Mr. Autry spoke about in his initial ERTS call. We found twelve unlabeled, full drums and two empties located in a false alley parallel to Jackson St and Mr. Warren numbered those drums. We noted this site is an old gas station but no longer dispenses gas but does do vehicle servicing (LOFs) and some minor repairs. There was also a For Sale sign on the top of the building. Realtor is David Behar 206 972-3983.

The operator of the site, Patrick Abe, said the drums had been there for about two years. They were generated through a site assessment and contained soil borings. Mr. Abe did not know if the analytical results indicated if any contained hazardous wastes. Mr. Abe gave us the land owner's name and phone number so we could follow up with him.

Additionally, Mr. Abe showed us a trench leading into a storm drain that Mr. Autry had wanted cleaned out. We took a picture of this for Mr. Autry's convenience as he was not able to meet us. Later, on 8/4/10, I talked with Mr. Autry and he said that he had also gone later and saw that everything he asked Mr. Abe to do was done.

We toured the site and asked Mr. Abe various questions about dangerous management as his facility. He told us that Emerald Services has been contracted to dispose of Used Oil and antifreeze. He uses up aerosol can products since they are expensive. We suggested the tire piles be moved inside or covered. The Used Oil tank should be marked as such. Mr. Walton gave him a pamphlet about fluorescent tube and electronics disposal.

The Compliance Unit will be sending a letter to Mr. Abe with the corrections he must make. Another will be sent to the landowner, asking for analytical results, directing him to label the drums, and arranging for them to be shipped offsite at:



Barry Mar 206 623-3732
DOTT MAR, INC
PO Box 3343
Seattle, WA 98114-3343

These letters and a photo log will be available in Central Records by the end of the month. A photo log can also be viewed on the X drive, NWRO ERTS Additional Information.



Photo Log



Photographer: Warren Walton


Witness: Trudy Harding

Area & Description	Photographs
<p>#1</p> <p>Partial Alley leading to 7th Ave</p> <p>Overview of 10 of 12 full – unlabeled drums.</p> <p>Two empty metal drums and one empty cardboard drum.</p>	 A photograph showing a narrow alleyway between a building and a parked car. In the foreground, there are several large metal drums (barrels) of various colors (black, blue, brown). Some are full, and some are empty. A cardboard box is on the ground. The alleyway leads towards a building with a large open bay door.
<p>#2</p> <p>Partial Alley leading to 7th Ave</p> <p>Drums numbered 1 and 2 plus marked empty drums.</p>	 A close-up photograph of several metal drums in the alleyway. Two drums in the foreground are clearly marked with white paint. One drum has 'MT 8-3' written on it, and another has '1 8-3-10'. There are other drums in the background, some with 'MT' markings.

Area & Description	Photographs
<p>#3</p> <p>Partial Alley leading to 7th Ave</p> <p>Numbered drums 1, 3, 4, 5, and 6.</p>	 A photograph showing a row of five black drums in an alleyway. The drums are numbered 1, 3, 4, 5, and 6. Each drum has the date '8-3-10' written on it. The drums are arranged in a line, and a portion of a car is visible in the background.
<p>#4</p> <p>Partial Alley leading to 7th Ave</p> <p>Drums numbered 7 and 8.</p>	 A photograph showing two black drums in an alleyway. The drums are numbered 7 and 8. Each drum has the date '8-3-10' written on it. The drums are arranged in a line, and a portion of a car is visible in the background.
<p>#5</p> <p>Partial Alley leading to 7th Ave</p> <p>Drums numbered 9 and 10.</p>	 A photograph showing two black drums in an alleyway. The drums are numbered 9 and 10. Each drum has the date '8-3-10' written on it. The drums are arranged in a line, and a portion of a car is visible in the background.

Area & Description	Photographs
<p>#6</p> <p>Side of Main Building, looking toward 7th Ave</p> <p>Drums numbered 11 and 12 sit in front of door on east side of office building.</p>	 A photograph showing two black metal drums sitting on a concrete step in front of a building. The drum on the left is marked with the number '11' and the date '8-3-10'. The drum on the right is marked with the number '12' and the date '8-3-10'. The building behind them has a rusted metal mesh fence.
<p>#7</p> <p>Partial Alley leading to 7th Ave</p> <p>Staining around the building was somewhat common. Owner at this location since 1972.</p>	 A photograph of a black metal drum in an alleyway. The drum is marked with the number '1' and the date '8-3-10'. The ground is gravel and dirt, and there is some debris and staining visible. A concrete step is visible in the background.

Area & Description	Photographs
<p>#8</p> <p>Overview</p> <p>Garage photo from across Jackson Way. Drums are behind the building and to the left of this picture</p>	 A photograph showing a street intersection. In the background, there is a multi-story building with a red facade. A traffic light pole is visible in the foreground. The street has a crosswalk with white stripes.
<p>#9</p> <p>Along 7th Avenue</p> <p>Looking along west side of building. Alley begins where the car is (in center).</p> <p>Drain leads to catchment basin (next photo).</p>	 A photograph of a narrow alleyway. On the left is a white concrete wall. A dark car is parked in the center of the alley. A metal drain grate is visible in the foreground, running along the wall. The alleyway leads to a street with parked cars and a yellow traffic cone.

Area & Description	Photographs
<p>#10</p> <p>Along 7th Avenue</p> <p>Catchment basin on south side of building between alley and street. Depth of basin unknown, but clearly there is mud and debris in the bottom.</p>	
<p>Comments:</p>	

HWTR Site Health and Safety Plan/Checklist

NOTE: *HWTR personnel are required to complete 40 hr HAZMAT training prior to conducting site visits at Hazardous Waste sites. All members of the inspection party must be briefed on this plan and have at least 24 hours of Safety Training.*

Site Name: 7th Ave Service, LLC ERTS ID#620637

Site Location: 701 South Jackson Seattle, WA

Site Contacts: Patrick Abe

Date: August 3, 2010 Arrival Time: _____

Name(s) of Ecology Personnel: Trudy Harding and Warren Walton

Are minimum training requirements met by all Ecology personnel? yes

Nearest Hospital: _____

Harborview Medical Center	325 Ninth Ave	Seattle	98104-2499	King	(206) 731-3000
---------------------------	---------------	---------	------------	------	----------------

Emergency Numbers: Statewide 911 Hospital: _____ Ambulance: _____

Site Description: Small engine repair and vehicle servicing (old gas station-no dispensing fuel)

Scope/Objective of Work: Complaint investigation

Known/Suspected Chemical Hazard(s):

- Corrosives Oxidizers Pesticides
 Nanomaterials Metals/Dust/Fume/Mist Flammables/Explosives

List if any of the following are known to be present:

Volatile Solvents: _____

Carcinogens: _____

Radioactive Materials: _____

Infectious/Bio-hazardous: _____

Hazardous Wastes: Used oil, antifreeze

Nanomaterials (location): _____

Other(s): _____

Routes of chemical exposure:

- Ingestion Inhalation Dermal No exposure

Overall risk of chemical exposure:

Serious Moderate Low Unknown

Known/Suspected Physical Hazard(s):

Confined space Unstable Piles Pits/Trenches Water
 Noise Steep Slopes Machinery
 Heat/cold stress Vehicle Traffic Slip/Trip/Falling Hazards

Other (specify): _____

If any area to be investigated is a confined/enclosed space, please describe:

Overall risk from physical hazards:

Serious Moderate Low Unknown

Protective Equipment:

Pre-visit PPE Level Selected: D

Comment:

Hardhat Safety Glasses Work Shoes
 Earplugs Goggles Steel-Toe/CPC Boots
 Raingear Face shield Booties

Gloves: outer/inner Type: _____

Coveralls/Tyvek/Saranex/Kappler

Level C Respiratory PPE: Full-face Half-face
Cartridge/Canister Type: _____

Was air monitoring conducted? Yes No
Prior to site entrance? Yes No

Type of air monitoring instrument used and results: _____

Site Departure Time: _____

Time Spent on Site: _____



License Detail

[Help us improve this online service](#)

License Information:

Entity Name: SEVENTH AVENUE SERVICE, LLC
Firm Name: SEVENTH AVENUE SERVICE
License Type: Washington State Business
Entity Type: Limited Liability Company
UBI: 602280825 Business ID:001 Location ID:0001

Location Address:

701 S JACKSON ST
SEATTLE, WA, 98104

Mailing Address:

701 S JACKSON ST
SEATTLE, WA, 98104

Licenses Held at this location:

[Underground Storage Tanks](#) [View Tanks](#)

License Status

[Active](#)

Expires

03/31/2009

First Issued

01/12/2009

Governing People:

PATRICK ABE

Registered Trade Names:

SEVENTH AVENUE SERVICE
SEVENTH AVENUE SERVICE, LLC

Information Current as of 08/03/2010 4:39AM Pacific Time

[New Search](#)

This site is limited to searching for business and professional licenses issued by the Department of Licensing or through the Master License Service. You may wish to click on [OTHER LICENSES](#) to check for information on licenses issued by other agencies.

[Department of Licensing Home](#) [Privacy Policy](#) [Other Licenses](#) [Contact Us](#)

Use of lists of individuals provided on this site for commercial purposes is prohibited under Chapter 42.56 of the Revised Code of Washington.

Corporations: Registration Detail

Corporations Division - Registration Data Search

Neither the State of Washington nor any agency, officer, or employee of the State of Washington warrants the accuracy, reliability, or timeliness of any information in the Public Access System and shall not be liable for any losses caused by such reliance on the accuracy, reliability, or timeliness of such information. While every effort is made to ensure the accuracy of this information, portions may be incorrect or not current. Any person or entity who relies on information obtained from the System does so at his or her own risk.

DOTT MAR, INC.

UBI Number	601293212
Category	REG
Profit/Nonprofit	Profit
Active/Inactive	Active
State Of Incorporation	WA
Date of Incorporation	12/31/1990
Expiration Date	12/31/2010
Dissolution Date	
Registered Agent Information	
Agent Name	BARRY MAR
Address	420 MAYNARD AVE S
City	SEATTLE
State	WA
ZIP	98114
Special Address Information	
Address	PO BOX 3343
City	SEATTLE 98114-3343

State WA
Zip 98114

Governing Persons

Title	Name	Address
Vice President	MAR , BARRY	SEATTLE , WA
Secretary	TOM , CAROL	FRESNO , CA
Treasurer	FUNG , BARBARA	FRESNO , CA
President	MAR , MARNIE	SAN JOSE , CA

[Purchase Documents for this Corporation »](#)

[« Return to Search List](#)

You can find this information at: http://www.sos.wa.gov/corps/search_detail.aspx?ubi=601293212