



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

1250 W Alder St • Union Gap, WA 98903-0009 • (509) 575-2490

October 7, 2020

David Hellyer and Terri Hellyer
P.O. Box 481
Chelan, WA 98816

RE: Updated property access to conduct environmental sampling

- **Site Name:** Chelan Chevron
- **Site Address:** 232 E. Woodin Avenue, Chelan
- **Facility/Site ID No.:** 77751227
- **Cleanup Site ID No.:** 6660

Dear David Hellyer & Terri Hellyer:

The Department of Ecology (Ecology) is overseeing an environmental investigation related to an old petroleum release at the above-referenced Site. Leidos, Inc., an environmental consultant to Chevron is performing the work. They need access to your property (136 E. Johnson Avenue, parcel number #272213512423) to sample the soil. Your property contains a groundwater monitoring well in the back parking area that was installed in 2003 under an existing access agreement. The previous sampling showed petroleum in the groundwater. Russell Shropshire of Leidos Inc. will contact you about updating the access agreement, if he has not already done so.

Ecology hopes you allow property access so we can learn more about the contamination. If you have any questions regarding this letter, please call me at (509) 731-9613 or email me at John.Mefford@ecy.wa.gov.


Sincerely,

John Mefford
Site Manager
Toxics Cleanup Program
Central Regional Office

Enclosure: Site Map with Proposed SRI Phase 5 Investigation Locations

cc: Ben Higgins and Jo Ann Higgins






- LEGEND**
- MW-2 EXISTING PERCHED GROUNDWATER MONITORING OR RECOVERY WELL
 - MW-30 EXISTING DEEP GROUNDWATER MONITORING WELL
 - MW-1 EXISTING ABANDONED DRY MONITORING WELL
 - SRI4B-2 SRI 4 SOIL BORING LOCATION
 - APPROXIMATE AREA OF SOIL BORING INVESTIGATION AT UNDOCUMENTED UST BASIN
 - APPROXIMATE AREA OF SUSPECTED UST BASIN (SEE GEOPHYSICAL SURVEY SUMMARY REPORT FOR ADDITIONAL LOCATION DETAILS)
 - PROPOSED UVOST-HP BORING LOCATION
 - PROPOSED SHALLOW SOIL BORING LOCATION
 - PROPOSED SOIL VAPOR PROBE LOCATION

NOTES

Base Map from City of Chelan, 1994

Additional Reference Material:
Aerial Photograph from September 1991
(Washington State Department of Natural Resources)

0 80' 160'



C:\Users\mhopster\Documents\Work_Files\Letos_Logs_Coltr_HighRes.jpg

Chevron Service Station No. 96590
232 East Woodin Avenue
Chelan, Washington

FIGURE 1
Site Map with Proposed SRI Phase 5
Investigation Locations

FILE NAME: Chelan_SRI-5 WP Site Map	DATE: 9/18/2020
--	--------------------