DEPARTMENT OF ECOLOGY State of Washington			Cleanup Site Details					Cleanup Site ID: 10035			
Cleanup Site ID: 100	035 <b>Facil</b>	ity/Site ID: 6	65138433	UST ID: 126	648	5	Site Page	Site Docu	iments	<u>View Map</u>	
Cleanup Site Name:	Moon Security S	Services Inc								<u>Glossary</u>	
Alternate Names: MOON SECURITY SERVICES INC											
LOCATION											
Address: 124 N 5TH	1		City: PASCO			Zip Code: 99301 County:				n	
Latitude: 46.23086	Longitude: -	119.09448	WRIA: 36	Legislative D	istrict:	16 <b>Co</b>	ongressiona	District:	4 TRS:	9N 30E 29	
DETAIL											
Status: No Further Action NFA			Received?			ls PSI s	site?	P No			
Statute: MTCA NFA			<b>Date:</b> 8/15/2011 <b>Current</b>				t VCP?	No Past	VCP? No		
Site Rank: N/A NFA			<b>Reason:</b> Initial Investigation			on Brownfield? No					
Site Manager: Eastern Region Rest			consible Unit: Eastern Active				Institutional Control? No				
CLEANUP UNITS											
Cleanup Unit Name Unit Type			Unit Status		Resp Unit	Unit	Unit Manager		Current Process		
Moon Security Services Inc Upland			No Further Action Required		EA			Independent Action			
ACTIVE INSTITUTIONAL CONTROLS											
Instrument Type Restriction Media Restriction			rictions/Requirements			Date Recordin Numbe			Recording County Tax P		
There are no current Institutional Controls in effect for this site.											
AFFECTED MEDIA & CONTAMINANTS											
Contaminant Petroleum-Other			Sc C		water	Surface	Water Se	diment	Air	Bedrock	
Key:											
Rey.B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below											
SITE ACTIVITIES											
Activity		5		Status S		art Date	Date End Date/ Completion Date				
LUST - Notification					Completed			6/18/1991			
LUST - Report Received					C	Completed			7/6/1992		
Site Status Changed to NFA						Completed		8/15/2011			