

Cleanup Site ID: 10036

Cleanup Site Details

Facility/Site ID: 65147793 UST ID: 1869 Site Page Site Documents View Map

Cleanup Site ID: 10036

Cleanup Site Name: Musics Tire Center Glossary

Alternate Names: MUSICS TIRE CENTER

LOCATION

Address: E 103 1ST AVE City: ODESSA Zip Code: 99159 County: Lincoln

Latitude: 47.33329 Longitude: -118.68906 WRIA: 43 Legislative District: 13 Congressional District: 5 TRS: 21N 33E 8

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 8/24/2011 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No

Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Musics Tire Center
 Upland
 No Further Action Required
 EA
 Eastern Region
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant Soil Groundwater Surface Water Sediment Air Bedrock
Petroleum-Other C

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

End Date/ Status **Start Date** Activity **Completion Date** LUST - Notification Completed 1/23/1991 LUST - Report Received Completed 2/11/1991 Site Status Changed to NFA Completed 8/24/2011 LUST - NFA Determination II or SHA Completed 8/24/2011

Toxics Cleanup Program Report Generated: 5/30/2025 Page 1 of 1