

Cleanup Site Details

Cleanup Site ID: 10048

Cleanup Site ID: 10048 **Facility/Site ID:** 65415931 **UST ID:** 200625 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Northern State Multi Service Center [Glossary](#)
Alternate Names: Northern State Multi Service Center, WA GA NORTHERN STATE MULTI SVC CTR, WA GA NORTHERN STATE MULTI-SVC CTI

LOCATION

Address: 2070 NORTHERN STATE RD **City:** SEDRO WOOLLEY **Zip Code:** 98284 **County:** Skagit
Latitude: 48.53025 **Longitude:** -122.20929 **WRIA:** 3 **Legislative District:** 39 **Congressional District:** 1 **TRS:** 35N 5E 7

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** Yes
Site Manager: DeBoer, Chris **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Northern State Multi Service Center LUST	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical Assistance Program
Northern State Multi Service Center	Upland	Cleanup Started	NW	DeBoer, Chris	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	S	S				
Halogenated Solvents		C				
Petroleum-Diesel	C	S				
Petroleum-Gasoline	C	S				
Petroleum-Other	C	S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		12/8/1992
Site Discovery/Release Report Received	Completed		12/8/1992
LUST - Report Received	Completed		4/20/1993
LUST - Report Received	Completed		4/20/1994

Cleanup Site Details

Cleanup Site ID: 10048

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		8/8/2011
Early Notice Letter(s)	Completed		3/4/2013
Order/Decree/Amendment	In Process	3/12/2019	
Interim Action - Plan	In Process	12/13/2019	
Remedial Investigation and/or FS Work Plan	In Process	12/16/2019	
Interim Action - Plan	In Process	1/29/2020	