

Cleanup Site Details

Cleanup Site ID: 10120

Cleanup Site ID: 10120 Facility/Site ID: 67416637 UST ID: 97716 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Clarkston High School Bus Garage [Glossary](#)

Alternate Names: Clarkston High School Bus Garage, TRANSPORTATION DEPARTMENT, TRANSPORTATION DEPARTMENT UST 97716

LOCATION

Address: 3RD & CHESTNUT City: CLARKSTON Zip Code: 99403 County: Asotin
 Latitude: 46.41105 Longitude: -117.04165 WRIA: 35 Legislative District: 9 Congressional District: 5 TRS: 11N 46E 21

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
 Site Rank: N/A NFA Reason: N/A Brownfield? No
 Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CLARKSTON HIGH SCHOOL BUS GARAGE	Upland	Cleanup Started	EA	Eastern Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/27/1989
LUST - Report Received	Completed		3/13/1989