

# Cleanup Site Details

Cleanup Site ID: 10120

Cleanup Site ID: 10120      Facility/Site ID: 67416637      UST ID: 97716      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Clarkston High School Bus Garage      [Glossary](#)

Alternate Names: Clarkston High School Bus Garage, TRANSPORTATION DEPARTMENT, TRANSPORTATION DEPARTMENT UST 97716

## LOCATION

Address: 3RD & CHESTNUT      City: CLARKSTON      Zip Code: 99403      County: Asotin  
Latitude: 46.41105      Longitude: -117.04165      WRIA: 35      Legislative District: 9      Congressional District: 5      TRS: 11N 46E 21

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: Eastern Region      Responsible Unit: Eastern      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
CLARKSTON HIGH SCHOOL BUS GARAGE	Upland	Cleanup Started	EA	Eastern Region	Independent Action

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/27/1989
LUST - Report Received	Completed		3/13/1989