

Cleanup Site Details

Cleanup Site ID: 10253

Cleanup Site ID: 10253 Facility/Site ID: 71657457 UST ID: 10145 Site Page Site Documents View Map

Cleanup Site Name: BP 11051

Alternate Names: BP 11051, BP STORE 5493, CIRCLE K - Kent, CIRCLE K 76 2705493, Circle K Store 5493 BP Oil, KAYO OIL 2705493, SW FM

720 CENTRAL, SWFM 720 Central, TOSCO FACILITY 05493

LOCATION

Address: 720 N CENTRAL City: KENT Zip Code: 98032 County: King

Latitude: 47.38706 Longitude: -122.23033 WRIA: 9 Legislative District: 33 Congressional District: 9 TRS: 22N 4E 13

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: PLIA Responsible Unit: Pollution Liability Ins Agcy Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BP 11051	Upland	Cleanup Started	PLIA	PLIA	PLIA Petroleum Technical

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С				
Other Non-Halogenated Organics	С	С				
Petroleum-Diesel		С				
Petroleum-Gasoline	С	С				
Petroleum-Other		С				

Key:

B - Below Cleanup Level S - Suspected C - Confirmed Above Cleanup Level R - Remediated RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		4/20/1994
LUST - Report Received	Completed		4/20/1994
Site Discovery/Release Report Received	Completed		4/20/1994
LUST - Report Received	Completed		8/29/1994
LUST - Report Received	Completed		2/23/1995

Toxics Cleanup Program Report Generated: 6/27/2025 Page 1 of 3



Cleanup Site Details

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		4/12/1995
LUST - Report Received	Completed		7/7/1995
LUST - Report Received	Completed		9/20/1995
LUST - Report Received	Completed		11/29/1995
LUST - Report Received	Completed		4/29/1996
LUST - Report Received	Completed		8/12/1996
LUST - Report Received	Completed		10/10/1996
LUST - Report Received	Completed		1/27/1997
LUST - Report Received	Completed		9/9/1997
LUST - Report Received	Completed		9/9/1997
LUST - Report Received	Completed		12/16/1997
LUST - Report Received	Completed		6/24/1998
LUST - Report Received	Completed		9/24/1998
LUST - Report Received	Completed		1/21/1999
LUST - Report Received	Completed		2/17/1999
LUST - Report Received	Completed		6/4/1999
LUST - Report Received	Completed		3/2/2000
LUST - Report Received	Completed		3/2/2000
LUST - Report Received	Completed		6/15/2000
LUST - Report Received	Completed		6/27/2000
LUST - Report Received	Completed		11/3/2000
LUST - Report Received	Completed		12/27/2000
LUST - Report Received	Completed		1/16/2002
LUST - Report Received	Completed		3/7/2002
LUST - Report Received	Completed		6/21/2002
LUST - Report Received	Completed		10/30/2002
LUST - Report Received	Completed		10/17/2003
LUST - Report Received	Completed		12/19/2003
LUST - Report Received	Completed		8/5/2004
LUST - Report Received	Completed		1/21/2005
LUST - Report Received	Completed		3/7/2006
LUST - Report Received	Completed		11/13/2006
LUST - Report Received	Completed		5/7/2007
LUST - Report Received	Completed		9/14/2007
LUST - Report Received	Completed		6/19/2008
Toxics Cleanup Program	Report Generated: 6/27/2025		Page 2 of 3



Cleanup Site Details

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
LUST - Report Received	Completed		1/30/2009		
LUST - Report Received	Completed		3/8/2011		
VCP Receipt of Plan or Report	Completed		4/26/2013		
VCP Opinion on Remedial Investigation	Completed	4/26/2013	7/22/2013		
LUST - Report Received	Completed		8/1/2013		
LUST - Report Received	Completed		7/8/2016		
VCP Receipt of Plan or Report	Completed		5/15/2017		

Cleanup Site ID: 10253