

Cleanup Site Details

Cleanup Site ID: 10346

Cleanup Site ID: 10346 Facility/Site ID: 73953138 UST ID: 3915 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Weyerhaeuser Snoqualmie Mill

[Glossary](#)

Alternate Names: SNOQUALMIE MILLSITE, SNOQUALMIE MILLSITE WEYERHAEUSER, WEYERHAEUSER SNOQUALMIE, Weyerhaeuser Snoqualmie Mill, Weyerhaeuser Snoqualmie Mill, Weyerhaeuser Snoqualmie Millsite

LOCATION

Address: 38800 SE MILL POND RD **City:** SNOQUALMIE **Zip Code:** 98065 **County:** King
Latitude: 47.53713 **Longitude:** -121.81896 **WRIA:** 7 **Legislative District:** 5 **Congressional District:** 1 **TRS:** 24N 8E 29

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: DeBoer, Chris **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Weyerhaeuser Snoqualmie Mill	Upland	Cleanup Started	NW	DeBoer, Chris	Independent Action
Borst Lake	Sediment	Awaiting Cleanup	NW	DeBoer, Chris	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Non-Halogenated Solvents	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C					
Phenolic Compounds	C			S		
Polychlorinated biPhenyls (PCB)	C					
Polycyclic Aromatic Hydrocarbons	C					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/6/1989
Site Discovery/Release Report Received	Completed		9/6/1989
LUST - Report Received	Completed		2/22/1990

Cleanup Site Details

Cleanup Site ID: 10346

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		7/11/1990
Early Notice Letter(s)	Completed		7/19/1990
LUST - Report Received	Completed		4/26/1991
LUST - Report Received	Completed		6/16/1992
LUST - Report Received	Completed		12/21/1992
Non-LUST Ind Report Received	Completed		1/25/2005
LUST - Report Received	Completed		3/9/2005
LUST - Report Received	Completed		3/9/2005
LUST - Report Received	Completed		3/9/2005
LUST - Report Received	Completed		3/9/2005
Site Hazard Assessment	Completed	9/18/2020	8/20/2021
Hazardous Sites Listing	Completed		8/23/2021