

Cleanup Site Details

Cleanup Site ID: 10377

Cleanup Site ID: 10377 Facility/Site ID: 74552527 UST ID: 2053 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: J H Kelly Inc

[Glossary](#)

Alternate Names: J H KELLY INC, JH Kelly LLC

LOCATION

Address: 821 3RD AVE City: LONGVIEW Zip Code: 98632 County: Cowlitz
Latitude: 46.12657 Longitude: -122.92637 WRIA: 25 Legislative District: 19 Congressional District: 3 TRS: 7N 2W 3

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 5/14/2019 Current VCP? No Past VCP? Yes
Site Rank: 2 - Moderate-High Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Fiedler, Aaren Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
J H KELLY INC	Upland	No Further Action Required	SW	Fiedler, Aaren	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Lead	B					
Methyl tertiary-butyl ether		RB				
Other Non-Halogenated Organics	B	RB				
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB	RB				
Petroleum-Other	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		11/18/1991
Site Discovery/Release Report Received	Completed		11/18/1991
LUST - Report Received	Completed		12/2/1991
LUST - Report Received	Completed		12/20/1991

Cleanup Site Details

Cleanup Site ID: 10377

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		6/9/1992
Initial Investigation / Federal Preliminary Assessment	Completed		12/13/2011
Early Notice Letter(s)	Completed		3/11/2013
LUST - Report Received	Completed		4/21/2013
Site Hazard Assessment	Completed	12/11/2013	1/30/2014
Hazardous Sites Listing	Completed		1/1/2016
VCP Receipt of Plan or Report	Completed		5/2/2016
LUST - Report Received	Completed		5/2/2016
VCP Opinion on Site Cleanup	Completed	5/2/2016	10/31/2016
VCP Technical Assistance	Completed		9/26/2017
VCP Technical Assistance	Completed		10/24/2017
LUST - Report Received	Completed		2/15/2018
LUST - Report Received	Completed		4/6/2018
LUST - Report Received	Completed		4/23/2018
LUST - Report Received	Completed		7/5/2018
LUST - Report Received	Completed		9/5/2018
LUST - Report Received	Completed		12/11/2018
VCP Opinion on Site Cleanup	Completed	12/11/2018	2/28/2019
Remove site from Hazardous Sites List	Completed		5/14/2019
Site Status Changed to NFA	Completed		5/14/2019