

Cleanup Site Details

Cleanup Site ID: 10377

Cleanup Site ID: 10377 **Facility/Site ID:** 74552527 **UST ID:** 2053 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: J H Kelly Inc [Glossary](#)
Alternate Names: J H KELLY INC, JH Kelly LLC

LOCATION

Address: 821 3RD AVE **City:** LONGVIEW **Zip Code:** 98632 **County:** Cowlitz
Latitude: 46.12657 **Longitude:** -122.92637 **WRIA:** 25 **Legislative District:** 19 **Congressional District:** 3 **TRS:** 7N 2W 3

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 5/14/2019 **Current VCP?** No **Past VCP?** Yes
Site Rank: 2 - Moderate-High Risk **NFA Reason:** Voluntary Cleanup Program Review **Brownfield?** No
Site Manager: Fiedler, Aaren **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
J H KELLY INC	Upland	No Further Action Required	SW	Fiedler, Aaren	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Lead	B					
Methyl tertiary-butyl ether		RB				
Other Non-Halogenated Organics	B	RB				
Petroleum-Diesel	RB	RB				
Petroleum-Gasoline	RB	RB				
Petroleum-Other	RB	RB				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		11/18/1991
Site Discovery/Release Report Received	Completed		11/18/1991
LUST - Report Received	Completed		12/2/1991
LUST - Report Received	Completed		12/20/1991

Cleanup Site Details

Cleanup Site ID: 10377

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		6/9/1992
Initial Investigation / Federal Preliminary Assessment	Completed		12/13/2011
Early Notice Letter(s)	Completed		3/11/2013
LUST - Report Received	Completed		4/21/2013
Site Hazard Assessment/Federal Site Inspection	Completed	12/11/2013	1/30/2014
Hazardous Sites Listing/NPL	Completed		1/1/2016
VCP Receipt of Plan or Report	Completed		5/2/2016
LUST - Report Received	Completed		5/2/2016
VCP Opinion on Site Cleanup	Completed	5/2/2016	10/31/2016
VCP Technical Assistance	Completed		9/26/2017
VCP Technical Assistance	Completed		10/24/2017
LUST - Report Received	Completed		2/15/2018
LUST - Report Received	Completed		4/6/2018
LUST - Report Received	Completed		4/23/2018
LUST - Report Received	Completed		7/5/2018
LUST - Report Received	Completed		9/5/2018
LUST - Report Received	Completed		12/11/2018
VCP Opinion on Site Cleanup	Completed	12/11/2018	2/28/2019
Remove site from Hazardous Sites List	Completed		5/14/2019
Site Status Changed to NFA	Completed		5/14/2019