

Cleanup Site Details

Cleanup Site ID: 1048

Cleanup Site ID: 1048	Facility/Site ID: 7738114	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Sterling Mine					Glossary
Alternate Names: Sterling Mine					

LOCATION

Address:			City: Metaline	Zip Code: 99153	County: Pend Oreille
Latitude: 48.83750	Longitude: -117.39120	WRIA: 62	Legislative District: 7	Congressional District: 5	TRS: 39N 43E 32

DETAIL

Status: Awaiting Cleanup	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Rice, Justin	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Sterling Mine	Upland	Awaiting Cleanup	CE	Rice, Justin	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals - Other	C					
Metals Priority Pollutants	C					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		6/25/2007
Early Notice Letter(s)	Completed		3/30/2008