DEPARTMENT OF ECOLOGY State of Washington	Cleanup Site Details						Cleanup Site ID: 1059			
Cleanup Site ID: 1059 Facili	ity/Site ID: 5	56816995	UST ID: N/A			Site Page	Site Docum	<u>ents</u>	<u>View Map</u>	
Cleanup Site Name: Atlas Mine & Mill								<u>Glossary</u>		
Alternate Names: Atlas Mine & Mill Supply Inc										
LOCATION										
Address: 1115 N HAVANA ST			City: SPOKA	Zip C	Zip Code: 99202 County: Spok			ne		
Latitude: 47.66861 Longitude: -1	17.34790	WRIA: 57	Legislative D	strict:	3 C a	ongressiona	al District: 5	TRS:	25N 43E 15	
DETAIL										
Status: No Further Action	NFA	Received?	Yes			ls PSI	site? No			
Statute: MTCA NFA Date:			1/15/2008 Current					VCP? No Past VCP? Yes		
Site Rank: N/A	Voluntary Clear	ntary Cleanup Program Review Brownfield? No								
Site Manager: Eastern Region Responsible Ur			Eastern	Eastern Active Ins				nstitutional Control? No		
CLEANUP UNITS										
Cleanup Unit Name	Unit Type	Unit	Status	Resp Unit	Unit	Manager	Current Process		cess	
Atlas Mine & Mill Supply Inc	Upland	Jpland No Further Action Required			Easte	rn Region	egion Standard		Voluntary Cleanup	
ACTIVE INSTITUTIONAL CONTROLS										
Instrument Type Restriction Restrictions/Red			rements	ents Dat		Recording Number			Tax Parcel	
There are no current Institutional Controls in effect for this site.										
AFFECTED MEDIA & CONTAMINANTS										
		MEDIA								
Contaminant Metals Priority Pollutants			il Ground	water	Surface	Water S	ediment	Air	Bedrock	
Petroleum Products-Unspecified			3							
Polychlorinated biPhenyls (PCB)			3							
Polycyclic Aromatic Hydrocarbons			3							
Key:										
Rey:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below										
SITE ACTIVITIES										
Activity				Status		S	tart Date	End Date/ Completion Date		
VCP Opinion on Cleanup Action		(Completed		3/8/2007	10/8/2007				
Site Status Changed to NFA				(Completed			1/15/2008		