

# Cleanup Site Details

Cleanup Site ID: 10609

Cleanup Site ID: 10609      Facility/Site ID: 81523572      UST ID: 100543      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Sedgwick 1 Stop      [Glossary](#)

Alternate Names: CI Sedgwick One Stop, SEDGWICK 1 STOP, SEDGWICK ONE STOP BP

## LOCATION

Address: 1701 SE SEDGWICK RD      City: PORT ORCHARD      Zip Code: 98366      County: Kitsap  
Latitude: 47.50527      Longitude: -122.63079      WRIA: 15      Legislative District: 26      Congressional District: 6      TRS: 23N 1E 1

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? Yes      Past VCP? Yes  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: Henderson, Cecilia      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Sedgwick One Stop BP	Upland	Cleanup Started	NW	Henderson, Cecilia	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Halogenated Solvents		S				
Non-Halogenated Solvents	C	C				
Petroleum-Diesel		S				
Petroleum-Gasoline	C	C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		6/6/2000
LUST - Report Received	Completed		6/6/2000
LUST - Site Assessment Report	Completed		7/10/2008
LUST - Report Received	Completed		8/20/2008
Site Discovery/Release Report Received	Completed		4/22/2009
Initial Investigation / Federal Preliminary Assessment	Completed		1/22/2010

# Cleanup Site Details

Cleanup Site ID: 10609

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		11/10/2010
LUST - Report Received	Completed		8/5/2011
VCP Status Request	Completed	2/28/2013	1/1/1900
VCP Opinion on Site Cleanup	Canceled	6/30/2015	1/1/1900
LUST - Report Received	Completed		10/19/2015
LUST - Report Received	Completed		1/6/2016
LUST - Report Received	Completed		12/9/2022
VCP Opinion on Remedial Investigation	Canceled	12/9/2022	1/1/1900
VCP Receipt of Plan or Report	Completed		8/18/2023
VCP Technical Assistance	Completed		8/21/2023
Site Hazard Assessment/Federal Site Inspection	Completed		3/26/2025