

# Cleanup Site Details

Cleanup Site ID: 10632

**Cleanup Site ID:** 10632      **Facility/Site ID:** 81966648      **UST ID:** 5046      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** Chevron 90129      [Glossary](#)  
**Alternate Names:** CHEVRON 0129, Chevron 90129, CHEVRON SS 90129, WASU Chevron

**LOCATION**

**Address:** 4700 BROOKLYN AVE NE      **City:** SEATTLE      **Zip Code:** 98105      **County:** King  
**Latitude:** 47.66335      **Longitude:** -122.31394      **WRIA:** 8      **Legislative District:** 43      **Congressional District:** 7      **TRS:** 25N 4E 8

**DETAIL**

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Myers, Dale R      **Responsible Unit:** Northwest      **Active Institutional Control?** No

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 90129	Upland	Cleanup Started	NW	Myers, Dale R	Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

**AFFECTED MEDIA & CONTAMINANTS**

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Petroleum-Gasoline	C	C				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected                      R - Remediated                                      RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		1/4/1990
LUST - Report Received	Completed		9/14/1990
LUST - Report Received	Completed		12/11/1990
LUST - Report Received	Completed		11/19/1991
LUST - Report Received	Completed		6/11/1992
LUST - Report Received	Completed		10/22/1992
LUST - Report Received	Completed		5/5/1993
LUST - Report Received	Completed		6/3/1993
LUST - Report Received	Completed		6/9/1993

# Cleanup Site Details

Cleanup Site ID: 10632

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/5/1994
LUST - Report Received	Completed		3/8/1994
LUST - Report Received	Completed		4/24/1995
LUST - Report Received	Completed		10/5/1995
LUST - Report Received	Completed		4/3/1996
LUST - Report Received	Completed		2/26/1997
LUST - Report Received	Completed		4/10/1998
LUST - Report Received	Completed		7/29/1999
LUST - Report Received	Completed		8/21/2000
LUST - Report Received	Completed		4/13/2001
LUST - Report Received	Completed		6/11/2001
LUST - Report Received	Completed		7/26/2001
LUST - Report Received	Completed		12/16/2002
LUST - Report Received	Completed		1/21/2003
LUST - Report Received	Completed		1/23/2004
LUST - Report Received	Completed		12/13/2004
LUST - Report Received	Completed		10/3/2005
LUST - Report Received	Completed		9/20/2006
LUST - Report Received	Completed		9/8/2009
LUST - Report Received	Completed		2/22/2010
LUST - Report Received	Completed		2/23/2011
LUST - Report Received	Completed		2/23/2011
LUST - Report Received	Completed		9/15/2011
LUST - Report Received	Completed		1/9/2012
Order/Decree/Amendment	In Process	11/15/2016	
LUST - Site Assessment Report	Completed		3/6/2017
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2017	10/5/2017
Remedial Investigation and/or Feasibility Study	In Process	5/26/2017	
Hazardous Sites Listing/NPL	Completed		10/6/2017
LUST - Report Received	Completed		3/9/2018
Interim Action - Plan	Completed		3/28/2018
Interim Action - Construction	Completed	3/28/2018	1/4/2019