

Cleanup Site Details

Cleanup Site ID: 10632

Cleanup Site ID: 10632 Facility/Site ID: 81966648 UST ID: 5046 [Site Page](#) [Site Documents](#) [View Map](#)
 Cleanup Site Name: Chevron 90129 [Glossary](#)
 Alternate Names: CHEVRON 0129, Chevron 90129, CHEVRON SS 90129, WASU Chevron

LOCATION

Address: 4700 BROOKLYN AVE NE City: SEATTLE Zip Code: 98105 County: King
 Latitude: 47.66335 Longitude: -122.31394 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 8

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
 Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
 Site Manager: Myers, Dale R Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron 90129	Upland	Cleanup Started	NW	Myers, Dale R	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Petroleum-Gasoline	C	C				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		1/4/1990
LUST - Report Received	Completed		9/14/1990
LUST - Report Received	Completed		12/11/1990
LUST - Report Received	Completed		11/19/1991
LUST - Report Received	Completed		6/11/1992
LUST - Report Received	Completed		10/22/1992
LUST - Report Received	Completed		5/5/1993
LUST - Report Received	Completed		6/3/1993
LUST - Report Received	Completed		6/9/1993

Cleanup Site Details

Cleanup Site ID: 10632

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/5/1994
LUST - Report Received	Completed		3/8/1994
LUST - Report Received	Completed		4/24/1995
LUST - Report Received	Completed		10/5/1995
LUST - Report Received	Completed		4/3/1996
LUST - Report Received	Completed		2/26/1997
LUST - Report Received	Completed		4/10/1998
LUST - Report Received	Completed		7/29/1999
LUST - Report Received	Completed		8/21/2000
LUST - Report Received	Completed		4/13/2001
LUST - Report Received	Completed		6/11/2001
LUST - Report Received	Completed		7/26/2001
LUST - Report Received	Completed		12/16/2002
LUST - Report Received	Completed		1/21/2003
LUST - Report Received	Completed		1/23/2004
LUST - Report Received	Completed		12/13/2004
LUST - Report Received	Completed		10/3/2005
LUST - Report Received	Completed		9/20/2006
LUST - Report Received	Completed		9/8/2009
LUST - Report Received	Completed		2/22/2010
LUST - Report Received	Completed		2/23/2011
LUST - Report Received	Completed		2/23/2011
LUST - Report Received	Completed		9/15/2011
LUST - Report Received	Completed		1/9/2012
Order/Decree/Amendment	In Process	11/15/2016	
LUST - Site Assessment Report	Completed		3/6/2017
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2017	10/5/2017
Remedial Investigation and/or Feasibility Study	In Process	5/26/2017	
Hazardous Sites Listing/NPL	Completed		10/6/2017
LUST - Report Received	Completed		3/9/2018
Interim Action - Plan	Completed		3/28/2018
Interim Action - Construction	Completed	3/28/2018	1/4/2019