

Cleanup Site ID: 10632

## Cleanup Site Details

Facility/Site ID: 81966648 UST ID: 5046 Site Page Site Documents View Map

Cleanup Site ID: 10632

Cleanup Site Name: Chevron 90129

Alternate Names: CHEVRON 0129, Chevron 90129, CHEVRON SS 90129, WASU Chevron

LOCATION

Address: 4700 BROOKLYN AVE NE City: SEATTLE Zip Code: 98105 County: King

Latitude: 47.66335 Longitude: -122.31394 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 8

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Treat, Nick Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

 
 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Chevron 90129
 Upland
 Cleanup Started
 NW
 Treat, Nick
 Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С				
Petroleum-Gasoline	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Respected R - Remediated RB - Respected RA - Respectively.

RA - Remediated-Above RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		1/4/1990
Site Discovery/Release Report Received	Completed		1/4/1990
LUST - Report Received	Completed		9/14/1990
LUST - Report Received	Completed		12/11/1990
LUST - Report Received	Completed		11/19/1991
LUST - Report Received	Completed		6/11/1992
LUST - Report Received	Completed		10/22/1992
LUST - Report Received	Completed		5/5/1993
LUST - Report Received	Completed		6/3/1993

Toxics Cleanup Program Report Generated: 10/24/2025 Page 1 of 2



**Toxics Cleanup Program** 

## Cleanup Site Details

ECOLOGY Cleanup Site Details		Clear	Cleanup Site ID: 10632			
SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Report Received	Completed		6/9/1993			
LUST - Report Received	Completed		1/5/1994			
LUST - Report Received	Completed		3/8/1994			
LUST - Report Received	Completed		4/24/1995			
LUST - Report Received	Completed		10/5/1995			
LUST - Report Received	Completed		4/3/1996			
LUST - Report Received	Completed		2/26/1997			
LUST - Report Received	Completed		4/10/1998			
LUST - Report Received	Completed		7/29/1999			
LUST - Report Received	Completed		8/21/2000			
LUST - Report Received	Completed		4/13/2001			
LUST - Report Received	Completed		6/11/2001			
LUST - Report Received	Completed		7/26/2001			
LUST - Report Received	Completed		12/16/2002			
LUST - Report Received	Completed		1/21/2003			
LUST - Report Received	Completed		1/23/2004			
LUST - Report Received	Completed		12/13/2004			
LUST - Report Received	Completed		10/3/2005			
LUST - Report Received	Completed		9/20/2006			
LUST - Report Received	Completed		9/8/2009			
LUST - Report Received	Completed		2/22/2010			
LUST - Report Received	Completed		2/23/2011			
LUST - Report Received	Completed		2/23/2011			
LUST - Report Received	Completed		9/15/2011			
LUST - Report Received	Completed		1/9/2012			
Order/Decree/Amendment	In Process	11/15/2016				
LUST - Site Assessment Report	Completed		3/6/2017			
Site Hazard Assessment	Completed	5/8/2017	10/5/2017			
Remedial Investigation and/or Feasibility Study	y Completed	5/26/2017	11/30/2022			
Hazardous Sites Listing	Completed		10/6/2017			
LUST - Report Received	Completed		3/9/2018			
Interim Action - Plan	Completed		3/28/2018			
Interim Action - Construction	Completed	3/28/2018	1/4/2019			
Remedial Investigation and/or Feasibility Study	y In Process	6/10/2024				
SHARP Assessment	Completed		7/16/2025			

Report Generated: 10/24/2025

Page 2 of 2