

Cleanup Site Details

Cleanup Site ID: 10635

Cleanup Site ID: 10635 Facility/Site ID: 82016954 UST ID: 11500 Site Page Site Documents View Map

Cleanup Site Name: Sundberg Gravel Pit Glossary

Alternate Names: COOPER POINT LOG YARD, Green Cove Sundberg Gravel Pit, Sundberg Gravel Pit

LOCATION

Address: 2200 COOPER PT RD City: OLYMPIA Zip Code: 98502 County: Thurston

Latitude: 47.06590 Longitude: -122.94213 WRIA: 13 Legislative District: 22 Congressional District: 10 TRS: 18N 2W 9

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Praisewater, Thomas Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SUNDBERG GRAVEL PIT	Upland	Cleanup Started	sw	Praisewater, Thomas	Independent Action
Sundberg Sediment	Sediment	Cleanup Started	sw	Praisewater, Thomas	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic	В	С	S	S			
Conventional Contaminants, Organic	S						
Lead	В	В					
Metals - Other	В	С	S	S			
Other Deleterious Substances	S			S			
Petroleum-Diesel	В	В					
Petroleum-Other	С	С		S			
Polycyclic Aromatic Hydrocarbons	С	В	S	S			

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		2/22/1993

Toxics Cleanup Program Report Generated: 11/12/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
Site Discovery/Release Report Received	Completed		2/22/1993			
LUST - Report Received	Completed		3/18/1993			
Initial Investigation / Federal Preliminary Assessment	Completed		1/5/2012			
LUST - NFA Determination II or SHA	Completed		8/15/2012			
Site Status Changed to NFA	Completed		8/15/2012			
Initial Investigation / Federal Preliminary Assessment	Completed		3/12/2019			
Reopen Site	Completed		6/18/2020			
Early Notice Letter(s)	Completed		8/3/2020			
Remedial Investigation and/or FS Work Plan	In Process	7/15/2021				
Order/Decree/Amendment	In Process	2/3/2022				

Cleanup Site ID: 10635