

## Cleanup Site Details

Cleanup Site ID: 11198

Cleanup Site ID: 11198 Facility/Site ID: 95362668 UST ID: 3262 Site Page Site Documents View Map

Cleanup Site Name: Texaco-Bulk Plant

Alternate Names: D & D DISTRIBUTORS, Texaco-Bulk Plant

LOCATION

Address: 606 Wagon Rd City: DAYTON Zip Code: 99328 County: Columbia

Latitude: 46.31519 Longitude: -117.99172 WRIA: 32 Legislative District: 16 Congressional District: 5 TRS: 10N 38E 25

**DETAIL** 

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 6/27/2017 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Ecology Supervised/Conducted Brownfield? No

Cleanup

Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TEXACO BULK PLANT	Upland	No Further Action Required	EA	Eastern Region	Ecology-supervised or conducted

## **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	В	В				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		7/17/1992
LUST - Report Received	Completed		7/17/1992
Petroleum Impacts to Groundwater Model Remedies	Completed		6/27/2017
Site Status Changed to NFA	Completed		6/27/2017

Toxics Cleanup Program Report Generated: 11/1/2025 Page 1 of 1