

Cleanup Site Details

Cleanup Site ID: 11198

Cleanup Site ID: 11198	Facility/Site ID: 95362668	UST ID: 3262	Site Page	Site Documents	View Map
Cleanup Site Name: Texaco-Bulk Plant					Glossary
Alternate Names: D & D DISTRIBUTORS, Texaco-Bulk Plant					

LOCATION

Address: 606 Wagon Rd			City: DAYTON	Zip Code: 99328	County: Columbia
Latitude: 46.31519	Longitude: -117.99172	WRIA: 32	Legislative District: 16	Congressional District: 5	TRS: 10N 38E 25

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 6/27/2017	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Ecology Supervised/Conducted Cleanup	Brownfield? No
Site Manager: Eastern Region	Responsible Unit: Eastern	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TEXACO BULK PLANT	Upland	No Further Action Required	EA	Eastern Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	B	B				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		7/17/1992
LUST - Report Received	Completed		7/17/1992
Petroleum Impacts to Groundwater Model Remedies	Completed		6/27/2017
Site Status Changed to NFA	Completed		6/27/2017