

# Cleanup Site Details

Cleanup Site ID: 11198

Cleanup Site ID: 11198      Facility/Site ID: 95362668      UST ID: 3262      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: TEXACO-BULK PLANT      [Glossary](#)

Alternate Names: D & D DISTRIBUTORS, TEXACO-BULK PLANT

## LOCATION

Address: 606 Wagon Rd      City: DAYTON      Zip Code: 99328      County: Columbia  
Latitude: 46.31519      Longitude: -117.99172      WRIA: 32      Legislative District: 16      Congressional District: 5      TRS: 10N 38E 25

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 6/27/2017      Current VCP? No      Past VCP? No  
Site Rank: N/A      NFA Reason: Ecology Supervised/Conducted Cleanup      Brownfield? No  
Site Manager: Eastern Region      Responsible Unit: Eastern      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
TEXACO BULK PLANT	Upland	No Further Action Required	EA	Eastern Region	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	B	B				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		7/17/1992
LUST - Report Received	Completed		7/17/1992
Petroleum Impacts to Groundwater Model Remedies	Completed		6/27/2017
Site Status Changed to NFA	Completed		6/27/2017