

Cleanup Site Details

Cleanup Site ID: 11246

Cleanup Site ID: 11246 Facility/Site ID: 96495686 UST ID: 11257 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: United Marine Shipbuilding [Glossary](#)

Alternate Names: MARINE POWER & EQUIPMENT CO INC, Propulsion Systems Inc, United Marine Shipbuilding

LOCATION

Address: 1441 N NORTHLAKE WAY City: SEATTLE Zip Code: 98103 County: King

Latitude: 47.64750 Longitude: -122.34128 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS:

DETAIL

| | | |
|---------------------------------------|------------------------------------|--|
| Status: Cleanup Started | NFA Received? No | Is PSI site? No |
| Statute: MTCA | NFA Date: N/A | Current VCP? No Past VCP? No |
| Site Rank: N/A | NFA Reason: N/A | Brownfield? No |
| Site Manager: Northwest Region | Responsible Unit: Northwest | Active Institutional Control? No |

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|----------------------------|-----------|-----------------|-----------|------------------|--------------------|
| United Marine Shipbuilding | Upland | Cleanup Started | NW | Northwest Region | Independent Action |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
|--------------------|------|-------------|---------------|----------|-----|---------|
| Benzene | C | | | | | |
| Petroleum-Gasoline | C | | | | | |
| Petroleum-Other | C | | | | | |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/Completion Date |
|--|-----------|------------|--------------------------|
| LUST - Notification | Completed | | 7/27/1989 |
| Site Discovery/Release Report Received | Completed | | 7/27/1989 |
| LUST - Report Received | Completed | | 8/1/1989 |
| LUST - Report Received | Completed | | 10/31/1989 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 8/8/2011 |
| Early Notice Letter(s) | Completed | | 5/17/2013 |