

# Cleanup Site Details

Cleanup Site ID: 11287

Cleanup Site ID: 11287      Facility/Site ID: 97679498      UST ID: 10604      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Arco 05923 Masad Nicola

[Glossary](#)

**Alternate Names:** ARCO 05923, Arco 05923 Masad Nicola, ARCO 5923, ARCO 5923 PSI 5460, ARCO FACILITY 05923 MASAD NICOLA, BP Service Station, Miller Property

## LOCATION

**Address:** 116 US HWY 12      **City:** CHEHALIS      **Zip Code:** 98532      **County:** Lewis  
**Latitude:** 46.54697      **Longitude:** -122.87303      **WRIA:** 26      **Legislative District:** 20      **Congressional District:** 3      **TRS:** 12N 2W 1

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** 5 - Lowest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Praisewater, Thomas      **Responsible Unit:** Southwest      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ARCO 05923 MASAD NICOLA	Upland	Cleanup Started	SW	Praisewater, Thomas	Standard Voluntary Cleanup Program

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	B			S	
Lead	C	RB				
Methyl tertiary-butyl ether	S	RB			S	
Non-Halogenated Solvents	C	B			S	
Other Non-Halogenated Organics		B				
Petroleum-Diesel	S	B				
Petroleum-Gasoline	C	B			S	
Petroleum-Other	C	RB				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Routine Cleanup	Completed		3/1/1993
Initial Investigation / Federal Preliminary Assessment	Completed		3/18/1993

# Cleanup Site Details

Cleanup Site ID: 11287

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		3/24/1993
LUST - Report Received	Completed		5/18/1993
LUST - Notification	Completed		4/1/1994
LUST - Report Received	Completed		4/1/1994
Site Hazard Assessment/Federal Site Inspection	Completed	9/25/2006	12/26/2006
Hazardous Sites Listing/NPL	Completed		12/26/2006
LUST - Notification	Completed		12/11/2009
Site Discovery/Release Report Received	Completed		12/11/2009
LUST - Report Received	Completed		5/5/2010
LUST - Report Received	Completed		1/31/2011
LUST - Report Received	Completed		9/29/2011
LUST - Report Received	Completed		9/29/2011
Initial Investigation / Federal Preliminary Assessment	Completed		12/12/2011
LUST - Report Received	Completed		5/31/2012
Early Notice Letter(s)	Completed		2/13/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		6/20/2013
LUST - Report Received	Completed		9/12/2013
LUST - Report Received	Completed		11/6/2013
LUST - Report Received	Completed		1/23/2014
LUST - Report Received	Completed		8/22/2014
VCP Opinion on Site Cleanup	Completed	10/20/2014	1/22/2015
LUST - Report Received	Completed		2/12/2015
VCP Opinion on Site Cleanup	Completed	10/8/2015	1/21/2016
VCP Opinion on Site Cleanup	Completed	4/1/2016	6/24/2016
VCP Opinion on Site Cleanup	Completed	4/1/2016	5/24/2016
VCP Receipt of Plan or Report	Completed		6/7/2017
LUST - Report Received	Completed		6/12/2017
VCP Receipt of Plan or Report	Completed		11/9/2017
VCP Receipt of Plan or Report	Completed		5/16/2018
VCP Receipt of Plan or Report	Completed		11/6/2018
LUST - Report Received	Completed		11/26/2018
Toxics Cleanup Program		Report Generated: 6/12/2025	Page 2 of 3

# Cleanup Site Details

Cleanup Site ID: 11287

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Remedial Investigation Work Plan	Completed	11/26/2018	4/23/2019
LUST - Report Received	Completed		2/21/2019
VCP Opinion on Site Cleanup	Canceled	10/23/2019	1/1/1900
LUST - Report Received	Completed		8/18/2020
LUST - Report Received	Completed		1/26/2021
VCP Receipt of Plan or Report	Completed		8/11/2021
VCP Receipt of Plan or Report	Completed		1/27/2022
VCP Receipt of Plan or Report	Completed		3/9/2022
VCP Receipt of Plan or Report	Completed		7/5/2022
VCP Receipt of Plan or Report	Completed		12/19/2022
VCP Receipt of Plan or Report	Completed		12/19/2022
VCP Opinion on Remedial Investigation	Completed	12/19/2022	5/16/2023
VCP Receipt of Plan or Report	Completed		7/3/2024
VCP Opinion on Remedial Investigation	Completed	8/13/2024	11/4/2024
SHARP Assessment	Completed		12/2/2024