

Cleanup Site Details

Cleanup Site ID: 11287

Cleanup Site ID: 11287 Facility/Site ID: 97679498 UST ID: 10604 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Arco 05923 Masad Nicola

[Glossary](#)

Alternate Names: ARCO 05923, Arco 05923 Masad Nicola, ARCO 5923, ARCO 5923 PSI 5460, ARCO FACILITY 05923 MASAD NICOLA, BP Service Station, Miller Property

LOCATION

Address: 116 US HWY 12 **City:** CHEHALIS **Zip Code:** 98532 **County:** Lewis
Latitude: 46.54697 **Longitude:** -122.87303 **WRIA:** 26 **Legislative District:** 20 **Congressional District:** 3 **TRS:** 12N 2W 1

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 5 - Lowest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Praisewater, Thomas **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ARCO 05923 MASAD NICOLA	Upland	Cleanup Started	SW	Praisewater, Thomas	Standard Voluntary Cleanup Program

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	B			S	
Lead	C	RB				
Methyl tertiary-butyl ether	S	RB			S	
Non-Halogenated Solvents	C	B			S	
Other Non-Halogenated Organics		B				
Petroleum-Diesel	S	B				
Petroleum-Gasoline	C	B			S	
Petroleum-Other	C	RB				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Routine Cleanup	Completed		3/1/1993
Initial Investigation / Federal Preliminary Assessment	Completed		3/18/1993

Cleanup Site Details

Cleanup Site ID: 11287

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		3/24/1993
LUST - Report Received	Completed		5/18/1993
LUST - Notification	Completed		4/1/1994
LUST - Report Received	Completed		4/1/1994
Site Hazard Assessment/Federal Site Inspection	Completed	9/25/2006	12/26/2006
Hazardous Sites Listing/NPL	Completed		12/26/2006
LUST - Notification	Completed		12/11/2009
Site Discovery/Release Report Received	Completed		12/11/2009
LUST - Report Received	Completed		5/5/2010
LUST - Report Received	Completed		1/31/2011
LUST - Report Received	Completed		9/29/2011
LUST - Report Received	Completed		9/29/2011
Initial Investigation / Federal Preliminary Assessment	Completed		12/12/2011
LUST - Report Received	Completed		5/31/2012
Early Notice Letter(s)	Completed		2/13/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		4/11/2013
LUST - Report Received	Completed		6/20/2013
LUST - Report Received	Completed		9/12/2013
LUST - Report Received	Completed		11/6/2013
LUST - Report Received	Completed		1/23/2014
LUST - Report Received	Completed		8/22/2014
VCP Opinion on Site Cleanup	Completed	10/20/2014	1/22/2015
LUST - Report Received	Completed		2/12/2015
VCP Opinion on Site Cleanup	Completed	10/8/2015	1/21/2016
VCP Opinion on Site Cleanup	Completed	4/1/2016	6/24/2016
VCP Opinion on Site Cleanup	Completed	4/1/2016	5/24/2016
VCP Receipt of Plan or Report	Completed		6/7/2017
LUST - Report Received	Completed		6/12/2017
VCP Receipt of Plan or Report	Completed		11/9/2017
VCP Receipt of Plan or Report	Completed		5/16/2018
VCP Receipt of Plan or Report	Completed		11/6/2018
LUST - Report Received	Completed		11/26/2018
Toxics Cleanup Program		Report Generated: 5/13/2025	Page 2 of 3

Cleanup Site Details

Cleanup Site ID: 11287

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Remedial Investigation Work Plan	Completed	11/26/2018	4/23/2019
LUST - Report Received	Completed		2/21/2019
VCP Opinion on Site Cleanup	Canceled	10/23/2019	1/1/1900
LUST - Report Received	Completed		8/18/2020
LUST - Report Received	Completed		1/26/2021
VCP Receipt of Plan or Report	Completed		8/11/2021
VCP Receipt of Plan or Report	Completed		1/27/2022
VCP Receipt of Plan or Report	Completed		3/9/2022
VCP Receipt of Plan or Report	Completed		7/5/2022
VCP Receipt of Plan or Report	Completed		12/19/2022
VCP Receipt of Plan or Report	Completed		12/19/2022
VCP Opinion on Remedial Investigation	Completed	12/19/2022	5/16/2023
VCP Receipt of Plan or Report	Completed		7/3/2024
VCP Opinion on Remedial Investigation	Completed	8/13/2024	11/4/2024