

# Cleanup Site Details

Cleanup Site ID: 11307 Facility/Site ID: 98422914 UST ID: 6275 Site Page Site Documents View Map

Cleanup Site ID: 11307

Cleanup Site Name: Terminal 115 Plant 1

Alternate Names: Crowley Marine Services Inc Terminal 115, Port of Seattle Terminal 115, SEATTLE PORT TERMINAL 115, TERMINAL 115,

Terminal 115 Plant 1

LOCATION

Address: 6020 W MARGINAL WAY City: SEATTLE Zip Code: 98106 County: King

Latitude: 47.54116 Longitude: -122.34277 WRIA: 9 Legislative District: 34 Congressional District: 7 TRS: 24N 4E 30

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Johnson, Beau Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Terminal 115 Plant 1	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

#### **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	n Restrictions/Requirements	rument Type Restrictio Media	Date	Recording Number	Recording County	Tax Parcel
-----------------	-----------------------------	---------------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Arsenic		S						
Benzene	С	С						
Lead	С	S						
Metals - Other	S	S						
Non-Halogenated Solvents	С							
Petroleum-Diesel	С	С						
Petroleum-Gasoline	С	С						
Polychlorinated biPhenyls (PCB)	S							
Polycyclic Aromatic Hydrocarbons	S							

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

### SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		5/6/1993

Toxics Cleanup Program Report Generated: 11/1/2025 Page 1 of 2



# Cleanup Site Details

Cleanup	Site	ID:	11307
---------	------	-----	-------

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		5/6/1993
LUST - Report Received	Completed		5/13/1993
LUST - Report Received	Completed		1/27/1994
LUST - Site Assessment Report	Completed		1/31/1994
LUST - Report Received	Completed		6/20/1994
LUST - Report Received	Completed		12/14/1994
LUST - Report Received	Completed		2/28/1995
LUST - Report Received	Completed		2/28/1995
LUST - Report Received	Completed		3/14/1995
LUST - Report Received	Completed		7/26/1995
LUST - Report Received	Completed		9/25/1995
LUST - Report Received	Completed		5/30/1996
LUST - Report Received	Completed		8/16/1996
LUST - Report Received	Completed		8/16/1996
LUST - Report Received	Completed		1/10/1997
LUST - Report Received	Completed		1/10/1997
LUST - Report Received	Completed		1/10/1997
LUST - Report Received	Completed		1/10/1997
LUST - Report Received	Completed		1/10/1997
LUST - Report Received	Completed		5/27/1997
LUST - Report Received	Completed		11/4/1997
Site Hazard Assessment	Completed	12/5/2014	6/8/2015
Hazardous Sites Listing	Completed		7/1/2015
Order/Decree/Amendment	In Process	9/4/2018	
Remedial Investigation and/or FS Work Plan	Planned	6/30/2025	6/30/2026
SHARP Assessment	Completed		9/30/2025