

# Cleanup Site Details

Cleanup Site ID: 1135

Cleanup Site ID: 1135      Facility/Site ID: 645      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Heglar Kronquist      [Glossary](#)

Alternate Names: HEGLAR KRONQUIST, Heglar Kronquist Site

## LOCATION

Address: HEGLAR RD & KRONQUIST RD      City: MEAD      Zip Code: 99021      County: Spokane  
Latitude: 47.78045      Longitude: -117.23717      WRIA: 55      Legislative District: 4      Congressional District: 5      TRS: 26N 44E 3

## DETAIL

Status: Construction Complete-Performance Monitoring      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 2 - Moderate-High Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Schrum, Kailey      Responsible Unit: Eastern      Active Institutional Control? Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Heglar Kronquist	Upland	Construction Complete-Performance Monitoring	EA	Schrum, Kailey	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater	Maintain/Protect Monitoring System	6/6/2013	13202067-4	Spokane	

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C	C	C		S	
Metals Priority Pollutants	C	C	C		S	

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		7/17/1985
Site Hazard Assessment/Federal Site Inspection	Completed	10/13/1987	12/13/1987
Site Hazard Assessment/Federal Site Inspection	Completed	2/15/2006	8/11/2006
Hazardous Sites Listing/NPL	Completed		8/23/2006
Order/Decree/Amendment	Completed	10/1/2008	6/6/2013
Remedial Investigation and/or Feasibility Study	Completed	4/15/2010	10/1/2013
Order/Decree/Amendment	In Process	1/1/2013	
Cleanup Action Plan	Completed	11/1/2013	2/1/2014

# Cleanup Site Details

Cleanup Site ID: 1135

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Cleanup - Construction	Completed	6/1/2014	9/1/2014
O & M	Completed	9/1/2014	6/1/2015
Cleanup - Performance Monitoring	In Process	9/1/2014	
O & M	Completed	6/1/2015	6/1/2016
O & M	Completed	6/1/2016	6/1/2017
O & M	Completed	6/1/2017	6/1/2018
O & M	Completed	6/1/2018	6/1/2019
O & M	Completed	6/1/2019	6/1/2020
O & M	In Process	6/1/2020	
Periodic Review	Completed	6/1/2020	12/1/2020
Periodic Review	Planned	6/1/2025	