

Cleanup Site Details

Cleanup Site ID: 11386

Cleanup Site ID: 11386 Facility/Site ID: 20168 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Cashmere Mill Site

Alternate Names: CASHMERE MILL SITE

LOCATION

Address: 5500 MILL RD City: CASHMERE Zip Code: 98815 County: Chelan

Latitude: 47.52106 Longitude: -120.47743 WRIA: 45 Legislative District: 12 Congressional District: 8 TRS: 23N 19E 5

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? Yes

Site Manager: Wise, Tavi Responsible Unit: Central Active Institutional Control? Yes

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------|-----------|-----------------|--------------|--------------|----------------------------|
| Cashmere Mill | Upland | Cleanup Started | CE | Wise, Tavi | Standard Voluntary Cleanup |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|---------------------------|----------------------|---|------------|---------------------|---------------------|---|
| Environmental Covenant | Groundwater, Soil | Restrict Land Use, Restrict All Ground Water Extraction/Well Installation | 10/12/2017 | 2466693 | Chelan | 231905141200; 231905110150; 231905141250; 231905924070 |

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

| | MEDIA | | | | | |
|----------------------------------|-------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Arsenic | | С | | | | |
| Mercury | С | | | | | |
| Petroleum-Gasoline | С | | | | | |
| Polycyclic Aromatic Hydrocarbons | С | | | | | |

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|------------------------------|
| Site Discovery/Release Report Received | Completed | | 11/13/2009 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 6/9/2010 |
| Early Notice Letter(s) | Completed | | 7/2/2010 |
| VCP Opinion on Property Cleanup | Completed | 3/10/2017 | 7/10/2017 |
| VCP Opinion on Property Cleanup | Completed | 10/12/2017 | 10/19/2017 |

Toxics Cleanup Program Report Generated: 10/23/2025 Page 1 of 2



Cleanup Site Details

| SITE ACTIVITIES | | | | | |
|---------------------------------|------------|------------|------------------------------|--|--|
| Activity | Status | Start Date | End Date/ Completion Date | | |
| Periodic Review | In Process | 7/12/2022 | | | |
| VCP Opinion on Property Cleanup | Completed | 12/1/2022 | 12/6/2023 | | |
| VCP Opinion on Property Cleanup | In Process | 1/24/2025 | | | |

Cleanup Site ID: 11386