

# Cleanup Site Details

Cleanup Site ID: 11420

**Cleanup Site ID:** 11420      **Facility/Site ID:** 19775      **UST ID:** N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** Stevens Pass Ski Resort Vehicle Maintenance Facility      [Glossary](#)  
**Alternate Names:** Stevens Pass Ski Resort Vehicle Maintenance Facility, Stevens Ski Resort Gear Oil Spill

## LOCATION

**Address:** 93001 NE Stevens Pass Hwy      **City:** Stevens Pass      **Zip Code:** 98288      **County:** King  
**Latitude:** 47.74460      **Longitude:** -121.08982      **WRIA:** 7      **Legislative District:** 39      **Congressional District:** 1      **TRS:** 26N 13E 14

## DETAIL

**Status:** No Further Action      **NFA Received?** Yes      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** 3/14/2013      **Current VCP?** No      **Past VCP?** Yes  
**Site Rank:** N/A      **NFA Reason:** Voluntary Cleanup Program Review      **Brownfield?** No  
**Site Manager:** Hepner, Norm      **Responsible Unit:** Central      **Active Institutional Control?** Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Vehicle Maintenance Facility	Upland	No Further Action Required	CE	Hepner, Norm	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Other Upland Instrument	Soil, Groundwater	Restrict All Ground Water Extraction/Well Installation, Prohibit Soil Disturbance	9/18/2012		King	

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RA	RB				
Petroleum-Gasoline	RA	RB				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		8/23/2010
Non-LUST Ind Report Received	Completed		8/30/2010
VCP Receipt of Plan or Report	Completed		2/11/2011
VCP Opinion on Site Cleanup Plan	Completed	2/11/2011	8/18/2011
VCP Receipt of Plan or Report	Completed		12/8/2011
VCP Opinion on Site Cleanup	Completed	12/8/2011	1/24/2012
VCP Receipt of Plan or Report	Completed		5/14/2012
VCP Receipt of Plan or Report	Completed		7/9/2012

# Cleanup Site Details

Cleanup Site ID: 11420

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
VCP Receipt of Plan or Report	Completed		10/2/2012
VCP Opinion on Site Cleanup	Completed	10/2/2012	3/14/2013
Site Status Changed to NFA	Completed		3/14/2013
Periodic Review	Completed	12/14/2017	6/14/2018
Periodic Review	Planned	4/1/2023	6/14/2023