

# Cleanup Site Details

**Cleanup Site ID: 11462**
**Cleanup Site ID:** 11462      **Facility/Site ID:** 29985737      **UST ID:** 2645      [Site Page](#)      [Site Documents](#)      [View Map](#)
**Cleanup Site Name:** BUSCH DISTRIBUTORS INC UST 2645      [Glossary](#)
**Alternate Names:** BUSCH DISTRIBUTORS INC UST 2645, STATELINE BULK PLANT/CARDLOCK

**LOCATION**
**Address:** 7603 SR 270      **City:** PULLMAN      **Zip Code:** 99163      **County:** Whitman  
**Latitude:** 46.73300      **Longitude:** -117.05006      **WRIA:** 34      **Legislative District:** 9      **Congressional District:** 5      **TRS:** 14N 46E 5

**DETAIL**

<b>Status:</b> No Further Action	<b>NFA Received?</b> Yes	<b>Is PSI site?</b> No
<b>Statute:</b> MTCA	<b>NFA Date:</b> 10/23/2015	<b>Current VCP?</b> No <b>Past VCP?</b> Yes
<b>Site Rank:</b> N/A	<b>NFA Reason:</b> Voluntary Cleanup Program Review	<b>Brownfield?</b> No
<b>Site Manager:</b> Eastern Region	<b>Responsible Unit:</b> Eastern	<b>Active Institutional Control?</b> No

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Busch Distributors, Inc. LUST	Upland	No Further Action Required	EA	Eastern Region	Standard Voluntary Cleanup

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

**AFFECTED MEDIA & CONTAMINANTS**
**MEDIA**

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB	RB				

**Key:**

B - Below Cleanup Level	C - Confirmed Above Cleanup Level	RA - Remediated-Above
S - Suspected	R - Remediated	RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/12/2010
Initial Investigation / Federal Preliminary Assessment	Completed		1/14/2011
Early Notice Letter(s)	Completed		1/14/2011
LUST - Report Received	Completed		1/26/2011
LUST - Notification	Completed		1/26/2011
LUST - Report Received	Completed		3/21/2011
LUST - Report Received	Completed		6/21/2011
LUST - Report Received	Completed		10/3/2011
LUST - Report Received	Completed		1/17/2012
LUST - Report Received	Completed		5/4/2012

# Cleanup Site Details

Cleanup Site ID: 11462

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
VCP Receipt of Plan or Report	Completed		1/18/2013
LUST - Report Received	Completed		2/15/2013
LUST - Report Received	Completed		6/12/2013
VCP Opinion on Site Cleanup Plan	Completed	7/17/2013	10/14/2013
VCP Opinion on Site Cleanup	Completed	9/23/2015	10/23/2015
Petroleum Impacts to Groundwater Model Remedies	Completed		10/9/2015
Site Status Changed to NFA	Completed		10/23/2015