

Cleanup Site Details

Cleanup Site ID: 11587

Cleanup Site ID: 11587 Facility/Site ID: 615198 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Spokane River Metals Barker Road North

[Glossary](#)

Alternate Names: SPOKANE RIVER METALS, Spokane River Metals Barker Road North, Spokane River Metals Barker Road South, Spokane River Metals Flora Road, Spokane River Metals Harvard Road, Spokane River Metals Island Complex, Spokane River Metals Islands Lagoon, Spokane River Metals Murray Road, Spokane River Metals Myrtle Point, Spokane River Metals Starr Road

LOCATION

Address: SPOKANE RIVER **City:** SPOKANE **Zip Code:** 99027 **County:** Spokane
Latitude: 47.68348 **Longitude:** -117.11165 **WRIA:** 57 **Legislative District:** 4 **Congressional District:** 5 **TRS:** 25N 45E 9

DETAIL

Status: Cleanup Complete-Active O&M/Monitoring **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Dowling, Brendan **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SPOKANE RIVER METALS BARKER ROAD NORTH	Sediment	Awaiting Cleanup	EA	Dowling, Brendan	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals - Other				C		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		12/1/1999