

Cleanup Site ID: 11592

Cleanup Site Details

Facility/Site ID: 23576 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 11592

Cleanup Site Name: Cape Disappointment Lighthouse Glossary

Alternate Names: Cape Disappointment Lighthouse

LOCATION

Address: Fort Canby State Park City: Ilwaco Zip Code: 98624 County: Pacific

Latitude: 46.27590 Longitude: -124.05223 WRIA: 24 Legislative District: 19 Congressional District: 3 TRS: 9N 11W 9

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 6/2/2011 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Federal Supervised/Conducted Brownfield? No

Cleanup

Site Manager: Rogowski, Barry Responsible Unit: Headquarters Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Cape Disappointment Lighthouse
 Upland
 No Further Action Required
 HQ
 Rogowski, Barry
 Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

			MED	IA	4		
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Lead	RA						

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		2/25/2002
Site Status Changed to NFA	Completed		6/2/2011
Periodic Review	Completed	6/10/2022	8/18/2022
Periodic Review	Planned	6/10/2027	1/1/1900

Toxics Cleanup Program Report Generated: 11/18/2025 Page 1 of 1