

Cleanup Site Details

Cleanup Site ID: 11592

Cleanup Site ID: 11592	Facility/Site ID: 23576	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Cape Disappointment Lighthouse					Glossary
Alternate Names: Cape Disappointment Lighthouse					

LOCATION

Address: Fort Canby State Park			City: Ilwaco	Zip Code: 98624	County: Pacific
Latitude: 46.27590	Longitude: -124.05223	WRIA: 24	Legislative District: 19	Congressional District: 3	TRS: 9N 11W 9

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 6/2/2011	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Federal Supervised/Conducted Cleanup	Brownfield? No
Site Manager: Rogowski, Barry	Responsible Unit: Headquarters	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Cape Disappointment Lighthouse	Upland	No Further Action Required	HQ	Rogowski, Barry	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	RA					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		2/25/2002
Site Status Changed to NFA	Completed		6/2/2011
Periodic Review	Completed	6/10/2022	8/18/2022
Periodic Review	Planned	8/18/2027	1/1/1900